



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Grey
Year of manufacture	2007
Top speed	120 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-30
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	106
Total items failed	17

**MOT #21**

2024-01-29 16:30

**MOT test number**

970743831684

**Result**

✓ Passed

**Next expiry date**

2025-01-30

- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Front Inner steering arm slight play
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Macpherson strut corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Bonnet release cable tight
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Turbo noisy
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Rear Coil spring corroded both heavily corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**MOT #20**

2024-01-27 11:01

**MOT test number**

428627384770

**Result****✗ Failed****Fail**

Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice**

Bonnet release cable tight

**Advice**

Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice**

Front Coil spring corroded both (5.3.1 (b) (i))

**Advice**

Turbo noisy

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Minor**

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Rear Macpherson strut corroded but not seriously weakened both (5.3.3 (b) (i))

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Offside Front Inner steering arm slight play

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice**

Rear Coil spring corroded both heavily corroded (5.3.1 (b) (i))

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Rear Lower Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

**Fail**

Central Rear Seat belt buckle not functioning as intended buckle damaged (7.1.2 (d))

**MOT #19**

2023-01-31 18:00

**MOT test number**

614075259463

**Result**

✓ Passed

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Covers fitted to front to rear brake and fuel pipes
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight seepage (6.1.7 (g) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))

**MOT #18**

2023-01-31 18:00

**MOT test number**

923544762925

**Result****✗ Failed****Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated slight seepage (6.1.7 (g) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))**Advice** Covers fitted to front to rear brake and fuel pipes**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #17**

2022-01-28 15:33

**MOT test number**

921593640375

**Result****✓ Passed**

**MOT #16**

2022-01-21 17:05

**MOT test number**

703999581021

**Result****✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #15**

2021-01-28 17:26

**MOT test number**

602523138239

**Result****✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))

**MOT #14**

2021-01-28 13:07

**MOT test number**

537441740340

**Result****✗ Failed**

- Advice** Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))
- Advice** Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))
- Fail** Front Tyre has ply or cords exposed both (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



**MOT #13** 2019-07-23 15:48**MOT test number** 939227766571**Result** ✓ Passed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**MOT #12** 2019-07-23 10:37**MOT test number** 777736666580**Result** ✗ Failed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #11** 2018-08-30 14:20**MOT test number** 212065691462**Result** ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**Advice** Offside Rear tyre worn low on inner edge.

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm.  
(5.3.4 (a) (i))

**MOT #10**

2018-08-30 14:20

**MOT test number**

189518358677

**Result****✗ Failed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm. (5.3.4 (a) (i))
- Advice** Offside Rear tyre worn low on inner edge.
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9**

2017-08-21 15:55

**MOT test number**

862133038297

**Result****✓ Passed**

- Advice** Engine cover and Under tray fitted.
- Advice** Central Rear Passenger seat(s) missing at time of test
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Diesel smoke levels high..
- Advice** Rear Passenger seat(s) missing at time of test most
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2016-08-08 15:09**MOT test number** 995426232981**Result** ✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Engine cover and Under tray fitted.
- Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2015-08-05 12:34**MOT test number** 637607315271**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Tow ball/hitch not fitted at time of test
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #6** 2014-08-11 11:04**MOT test number** 588613524262**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**MOT #5** 2013-08-07 14:39**MOT test number** 716579813283**Result** ✓ Passed**Notice** Tow ball/hitch not fitted at time of test**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-08-28 13:41**MOT test number** 876111542223**Result** ✓ Passed



MOT #3	2011-08-18 14:28
MOT test number	987590531247
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-09-09 10:06
MOT test number	123102650277
Result	✓ Passed

MOT #1	2010-09-08 16:38
MOT test number	974511650266
Result	✗ Failed
Fail	Centre Stop lamp not working (1.2.1b)



Tax & MOT check

X

Untaxed

Tax expired:  
5 April 2024

✓

MOT

Expires:  
30 January 2025

Tax status	Expired at 5 April 2024
Days left	24 days too late
MOT expiry date	30 January 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>LN57ZDH</b>
Plate since	2019-03-29
Current registration	<b>LN57ZDH</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-09-12
Last registration	2024-01-29
Complete history	<a href="#">See info</a>



Registration #1	2007-09-12	20 mi
Registration #2	2010-09-08	25.870 mi
Registration #3	2010-09-09	25.870 mi
Registration #4	2011-08-18	34.377 mi
Registration #5	2012-08-28	41.748 mi
Registration #6	2013-08-07	49.967 mi
Registration #7	2014-08-11	56.693 mi
Registration #8	2015-08-05	63.191 mi
Registration #9	2016-08-08	68.040 mi
Registration #10	2017-08-21	75.552 mi
Registration #11	2018-08-30	86.698 mi
Registration #12	2018-08-30	86.698 mi
Registration #13	2019-08-29	95.377 mi
Registration #14	2019-08-29	95.377 mi
Registration #15	2019-08-29	95.377 mi
Registration #16	2019-08-29	95.377 mi
Registration #17	2019-08-29	95.377 mi
Registration #18	2019-08-29	95.377 mi
Registration #19	2019-08-29	95.377 mi
Registration #20	2019-08-29	95.377 mi
Registration #21	2019-08-29	95.377 mi
Registration #22	2019-08-29	95.377 mi
Registration #23	2019-08-29	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	7T68790