



PEUGEOT



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | PEUGEOT |
| Model | 206 HDI ZEST 3 |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 104 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 67 BHP |
| Max. torque | 160 Nm at 1.750 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 51.4 mpg |
| Consumption extra urban | 78.5 mpg |
| Consumption combined | 65.7 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-19 |
| Pictures | 19 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

| | |
|-------------------------|---|
| MOT #25 | 2023-02-10 15:37 |
| MOT test number | 313078040044 |
| Result | ✓ Passed |
| Next expiry date | 2024-02-09 |
| Advice | Nearside Front Shock mount corroded and in poor condition |
| Advice | Front Coil spring corroded (5.3.1 (b) (i)) |
| Advice | Front Anti roll bar D rubbers in poor condition |

| | |
|------------------------|--|
| MOT #24 | 2022-09-28 12:44 |
| MOT test number | 398213264734 |
| Result | ✗ Failed |
| Advice | N/s front top shock mount corrded and in poor condition |
| Fail | Offside Rear Upper Shock absorbers has an excessively worn bush bush / bolt worn to excess (5.3.2 (c)) |
| Advice | Number plate light out |
| Fail | Brake hose ferrule excessively corroded and likely to fail both rear hoses (1.1.12 (f) (ii)) |
| Advice | O/s front wish bone arm bushes in poor condition / worn |
| Fail | Exhaust system insecure front pipe (6.1.2 (a)) |
| Advice | Front anti roll bar d rubbers in poor condition |
| Advice | N/s front brake hose steel end in poor condition |
| Fail | Offside Front Brake hose ferrule excessively corroded and likely to fail (1.1.12 (f) (ii)) |
| Advice | Slight leak from n/s front outer cv boot |
| Fail | Sub-frame ball joint excessively worn both front lower ball joints (5.3.4 (a) (i)) |
| Fail | Exhaust system insecure rear box clamp corrded to excess (6.1.2 (a)) |
| Advice | Noise from o/s front outer cv joint |
| Advice | Front coil springs in poor condition |

**MOT #23**

2022-08-26 11:14

MOT test number

128270063522

Result

✗ Failed

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (ii))
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #22

2021-09-20 13:18

MOT test number

811470179505

Result

✓ Passed

- Advice** Nearside Front Suspension arm ball joint has slight play bottom ball joint (5.3.4 (a) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement radius arm bush (5.3.4 (a) (i))

MOT #21

2020-09-22 07:49

MOT test number

781870759118

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge slightly wearing on inner edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Rear Position lamp slightly affected by the operation of another lamp offside and nearside when indicators or hazards on (4.2.3 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material x1 by fuel tank within clip in area (1.1.11 (c))

**MOT #20**

2020-09-22 07:49

MOT test number

536831501433

Result**✗ Failed****Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Position lamp slightly affected by the operation of another lamp offside and nearside when indicators or hazards on (4.2.3 (c))**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge slightly wearing on inner edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material x1 by fuel tank within clip in area (1.1.11 (c))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Pass with rectification** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**MOT #19**

2019-06-04 10:00

MOT test number

978701731982

Result**✓ Passed****Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #18**

2019-06-04 10:00

MOT test number

158560192935

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))



| | |
|------------------------|----------------------------|
| MOT #17 | 2018-06-07 14:27 |
| MOT test number | 349034243260 |
| Result | ✓ Passed |
| Advice | Offside Rear tyre perished |

| | |
|------------------------|---|
| MOT #16 | 2018-06-07 08:54 |
| MOT test number | 858028263277 |
| Result | ✗ Failed |
| Fail | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Fail | Fuel tank insecure (6.1.3 (a) (i)) |
| Fail | Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) |
| Advice | Offside Rear tyre perished |

| | |
|------------------------|------------------|
| MOT #15 | 2017-06-08 08:08 |
| MOT test number | 161325115832 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #14 | 2016-06-14 14:14 |
| MOT test number | 636999144582 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #13 | 2016-06-14 10:59 |
| MOT test number | 596020962179 |
| Result | ✗ Failed |
| Fail | Offside Front Shock absorber has a serious fluid leak (2.7.3) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

**MOT #12**

2015-07-31 13:34

MOT test number

395562815400

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Nail in offside rear tyre**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** N/S/F WIPER HAS A SLIGHT SMEAR**MOT #11**

2015-07-31 12:33

MOT test number

558652315213

Result

✗ Failed

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** N/S/F WIPER HAS A SLIGHT SMEAR**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Nail in offside rear tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Seat belt retracting mechanism defective (5.2.5b)**MOT #10**

2014-08-04 16:13

MOT test number

377176314218

Result

✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #9** 2013-08-01 14:51**MOT test number** 479913513286**Result** ✓ Passed**MOT #8** 2013-08-01 13:27**MOT test number** 339573713443**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim too high (1.8)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2012-07-10 12:19**MOT test number** 579402892178**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** BOTH front disc slightly corroded on inner face**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/f wiper has a slight smear

**MOT #6** 2012-07-10 08:59**MOT test number** 388622892118**Result** ✗ Failed

- Notice** O/s/f wiper has a slight smear
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** BOTH front disc slightly corroded on inner face
- Fail** Nearside Front Upper coil spring incomplete (2.4.C.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2011-07-12 13:43**MOT test number** 655983991126**Result** ✓ Passed

- Advice** Nearside Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #4 2010-07-13 14:54**MOT test number** 721094590177**Result** ✓ Passed

- Notice** FRONT DISCS INNER FACES CORRODED

MOT #3 2010-07-13 13:08**MOT test number** 133644490170**Result** ✗ Failed

- Fail** Stop lamp not working (1.2.1b)
- Notice** FRONT DISCS INNER FACES CORRODED



| | |
|-----------------|------------------|
| MOT #2 | 2009-05-27 09:18 |
| MOT test number | 232727449433 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2008-06-16 15:19 |
| MOT test number | 660148368198 |
| Result | ✓ Passed |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 27 |
| First mileage registration | 2005-07-28 |
| Last registration | 2023-02-10 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2005-07-28 | 15 mi |
| Registration #2 | 2008-06-16 | 23.159 mi |
| Registration #3 | 2009-05-27 | 24.496 mi |
| Registration #4 | 2010-07-13 | 29.442 mi |
| Registration #5 | 2010-07-13 | 29.442 mi |
| Registration #6 | 2011-07-12 | 36.833 mi |
| Registration #7 | 2012-07-10 | 44.940 mi |
| Registration #8 | 2012-07-10 | 44.948 mi |
| Registration #9 | 2013-08-01 | 51.408 mi |
| Registration #10 | 2013-08-01 | 51.408 mi |
| Registration #11 | 2014-08-04 | 60.257 mi |
| Registration #12 | 2015-07-31 | 63.473 mi |
| Registration #13 | 2015-07-31 | 63.478 mi |
| Registration #14 | 2016-06-14 | 66.115 mi |
| Registration #15 | 2016-06-14 | 66.115 mi |
| Registration #16 | 2016-06-14 | 66.115 mi |
| Registration #17 | 2016-06-14 | 66.115 mi |
| Registration #18 | 2016-06-14 | 66.115 mi |
| Registration #19 | 2016-06-14 | 66.115 mi |
| Registration #20 | 2016-06-14 | 66.115 mi |
| Registration #21 | 2016-06-14 | 66.115 mi |
| Registration #22 | 2016-06-14 | 66.115 mi |
| Registration #23 | 2016-06-14 | 66.115 mi |
| Registration #24 | 2016-06-14 | 66.115 mi |
| Registration #25 | 2016-06-14 | 66.115 mi |
| Registration #26 | 2016-06-14 | 66.115 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1652 mm |
| Height | 1433 mm |
| Length | 3822 mm |
| Wheel base | 2445 mm |
| Kerb weight | 1049 kg |
| Max. allowed weight | 1525 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 5 |

| | |
|------------------------|-------------|
| Number of axles | 2 |
| Engine number | FD621220270 |