



report date: 2024-03-28

General information

Make	KIA
Model	MAGENTIS 16V SE
Colour	Red
Year of manufacture	2006
Top speed	121 mph
0 - 60 mph	11.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	179 Nm at 4.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.4 mpg
CO2 emission	220 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	27
Total items failed	12

MOT #18	2023-07-17 12:33
MOT test number	871717711295
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

MOT #17	2022-07-11 09:00
MOT test number	439845635070
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2021-07-16 13:43
MOT test number	276059189368
Result	✓ Passed

MOT #15	2020-03-11 13:18
MOT test number	499394446899
Result	✓ Passed

**MOT #14**

2020-01-11 10:52

MOT test number

214918030134

Result**✗ Failed****Fail**

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Os wiper blade deteriorated

Fail

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Front Registration plate inscription illegible (0.1 (b))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Fail

Offside Rear Tyre tread depth below requirements of 1.6mm 2056015 (5.2.3 (e))

MOT #13

2019-01-26 11:34

MOT test number

687448512270

Result**✓ Passed****Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #12**

2019-01-25 12:03

MOT test number

711946021474

Result**✗ Failed**

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11

2018-01-15 13:32

MOT test number

231922054561

Result**✓ Passed**

- Advice** Offside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #10** 2017-01-18 13:06**MOT test number** 345081452439**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Oil leak**MOT #9** 2016-01-21 16:50**MOT test number** 228855138950**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-01-17 09:57**MOT test number** 165337315051**Result** ✓ Passed**Notice** Both front tyres starting to wear on inner edges**MOT #7** 2014-01-17 19:55**MOT test number** 248517014077**Result** ✓ Passed**MOT #6** 2013-01-24 18:23**MOT test number** 276664223024**Result** ✓ Passed**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Inner Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2012-01-27 16:42**MOT test number** 118097422008**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-01-27 16:42**MOT test number** 199297722422**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2011-01-28 15:58**MOT test number** 918388321089**Result** ✓ Passed**MOT #2** 2010-01-18 12:48**MOT test number** 163988010006**Result** ✓ Passed**MOT #1** 2009-01-27 14:57**MOT test number** 770257829007**Result** ✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	RY55TKA
Plate since	2019-09-28
Current registration	RY55TKA
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-01-31
Last registration	2023-07-17
Complete history	See info



Registration #1	2006-01-31	9 mi
Registration #2	2009-01-27	23.318 mi
Registration #3	2010-01-18	30.172 mi
Registration #4	2011-01-28	37.054 mi
Registration #5	2012-01-27	42.259 mi
Registration #6	2013-01-24	48.760 mi
Registration #7	2014-01-17	55.695 mi
Registration #8	2015-01-17	62.638 mi
Registration #9	2016-01-21	71.767 mi
Registration #10	2017-01-18	79.968 mi
Registration #11	2018-01-20	88.217 mi
Registration #12	2019-01-20	96.517 mi
Registration #13	2020-01-20	104.867 mi
Registration #14	2021-01-20	113.267 mi
Registration #15	2022-01-20	121.717 mi
Registration #16	2023-01-20	130.217 mi
Registration #17	2024-01-20	138.767 mi
Registration #18	2025-01-20	147.267 mi
Registration #19	2026-01-20	155.817 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1820 mm
Height	1410 mm
Length	4730 mm
Wheel base	2700 mm
Kerb weight	1490 kg
Max. allowed weight	1985 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	G4JP5202709