



General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Blue
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2021-06-08
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	7
Total items failed	3

MOT #10	2020-06-09 15:04
MOT test number	216523195848
Result	✓ Passed
Next expiry date	2021-06-08

MOT #9	2020-06-03 09:56
MOT test number	564822018718
Result	✗ Failed
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #8	2019-07-17 11:20
MOT test number	687937327547
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2018-07-13 11:23
MOT test number	269940934187
Result	✓ Passed

**MOT #6** 2017-07-05 09:40**MOT test number** 904302797188**Result** ✓ Passed**MOT #5** 2017-07-05 09:40**MOT test number** 557903020537**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on main beam (1.7.5a)**MOT #4** 2016-07-28 10:48**MOT test number** 600742090307**Result** ✓ Passed**MOT #3** 2015-05-05 10:59**MOT test number** 265765025424**Result** ✓ Passed**Notice** Nearside front tyre is wearing slightly on shoulders**Notice** Front wipers smearing slightly**MOT #2** 2015-05-05 10:59**MOT test number** 149585025139**Result** ✗ Failed**Notice** Nearside front tyre is wearing slightly on shoulders**Notice** Front wipers smearing slightly**Pass with rectification** Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #1** 2014-03-27 16:12**MOT test number** 447066584017**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 March 2021

X

MOT

Expired:
8 June 2021

Tax status	Expired at 31 March 2021
Days left	1126 days too late
MOT expiry date	8 June 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-03-24
Last registration	2020-06-09
Complete history	See info



Registration #1	2011-03-24	28 mi
Registration #2	2014-03-27	11.397 mi
Registration #3	2015-05-05	15.097 mi
Registration #4	2016-07-28	18.569 mi
Registration #5	2017-07-05	19.997 mi
Registration #6	2017-07-05	19.997 mi
Registration #7	2019-06-09	20.000 mi
Registration #8	2019-06-09	20.000 mi
Registration #9	2019-06-09	20.000 mi
Registration #10	2019-06-09	20.000 mi
Registration #11	2019-06-09	20.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305