



General information

Make	AUDI
Model	Q5 TDI QUATTRO DPF S LINE
Colour	Silver
Year of manufacture	2010
Top speed	126 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2022-11-14
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-06-12
Pictures	87
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-12
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	38
Total items failed	5

MOT #14 2023-12-05 10:23

MOT test number 629648174131

Result ✓ Passed

Next expiry date 2024-12-12

Advice Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

Advice Offside Front Upper Suspension arm ball joint has slight play Front and back (5.3.4 (a) (i))

Advice Nearside Front Upper Suspension arm ball joint has slight play Front and back (5.3.4 (a) (i))

MOT #13 2022-12-13 13:10

MOT test number 952750140641

Result ✓ Passed

MOT #12 2021-07-26 09:28

MOT test number 222235164773

Result ✓ Passed

Advice Offside Front Play in steering rack inner joint(s)

MOT #11 2021-01-26 08:39

MOT test number 579751465429

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre on legal limit 1.6mm (5.2.3 (e))

**MOT #10**

2021-01-23 08:57

MOT test number

874436263977

Result

✗ Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn arm inner bush to subframe and lower shocker bush deteriorated (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tyre on legal limit 1.6mm (5.2.3 (e))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn inner bush to subframe (5.3.4 (a) (i))

MOT #9

2020-01-25 08:06

MOT test number

802787868923

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge n/s and o/s rear tyres close to limit (5.2.3 (e))

Advice Suspension arm pin or bush worn but not resulting in excessive movement n/s and o/s front lower suspension arms inner bushes worn (5.3.4 (a) (i))

Advice Shock absorbers has a slightly worn bush n/s and o/s front lower shocker bushes worn (5.3.2 (c))

MOT #8

2019-01-28 09:16

MOT test number

276431911071

Result

✓ Passed

Advice Engine cover and under trays fitted

Advice Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on 1.6 outer edge (5.2.3 (e))

MOT #7

2018-01-15 12:57

MOT test number

292465457325

Result

✓ Passed

Advice Nearside Front Brake pad(s) wearing thin and offside front (3.5.1g)

Advice Engine cover fitted and under trays

**MOT #6** 2017-01-14 08:30**MOT test number** 139482245567**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-01-28 13:43**MOT test number** 529311534544**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #4** 2014-08-27 14:29**MOT test number** 837799034220**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #3** 2014-08-25 16:27**MOT test number** 348807234234**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-08-28 16:37**MOT test number** 245410443209**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #1

2013-08-28 10:36

MOT test number

179040643284

Result

✗ Failed

- Fail

Front registration plate insecure (6.3.1b)
- Notice

Nail in nearside rear tyre
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice

Engine covers fitted obscuring some components in the engine bay
- Fail

Parking brake: efficiency below requirements (3.7.B.7)
- Notice

Under-trays fitted obscuring some underside components
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	KX10XJO
Plate since	2024-03-29
Current registration	KX10XJO
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-15
Last registration	2023-12-05
Complete history	See info



Registration #1	2010-03-15	15 mi
Registration #2	2013-08-28	37.437 mi
Registration #3	2013-08-28	37.437 mi
Registration #4	2014-08-25	48.541 mi
Registration #5	2014-08-27	48.541 mi
Registration #6	2016-01-28	64.702 mi
Registration #7	2017-01-14	75.355 mi
Registration #8	2018-01-15	85.853 mi
Registration #9	2019-01-28	95.801 mi
Registration #10	2020-01-28	105.801 mi
Registration #11	2020-01-28	105.801 mi
Registration #12	2020-01-28	105.801 mi
Registration #13	2020-01-28	105.801 mi
Registration #14	2020-01-28	105.801 mi
Registration #15	2020-01-28	105.801 mi
Registration #16	2020-01-28	105.801 mi
Registration #17	2020-01-28	105.801 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	84%
Pedestrian	32%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1653 mm
Length	4629 mm
Wheel base	2807 mm
Kerb weight	1730 kg
Max. allowed weight	2355 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAH 086142