



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI GS
Colour	Green
Year of manufacture	2001
Top speed	109 mph
0 - 60 mph	9.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	35.3 mpg
CO2 emission	192 g/km
CO2 label	J





MOT history

MOT expiry date	2021-11-02
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	26
Total items failed	6

MOT #20	2020-10-26 14:05
MOT test number	503523969860
Result	✓ Passed
Next expiry date	2021-11-02
Advice	Front and rear suspension bushes crackling
Advice	Front subframe and rear axel rusty
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #19	2020-10-26 14:05
MOT test number	375091556830
Result	✗ Failed
Advice	Front and rear suspension bushes crackling
Advice	Child Seat fitted not allowing full inspection of adult belt
Pass with rectification	Headlamp aim too low both (4.1.2 (a))
Advice	Front subframe and rear axel rusty

**MOT #18** 2019-10-14 14:00**MOT test number** 878129772171**Result** ✓ Passed**Advice** Noisy baffels in manifold**Advice** Noise baffels from manifold**MOT #17** 2019-10-14 09:51**MOT test number** 139528429140**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2018-10-23 08:40**MOT test number** 117815567513**Result** ✓ Passed**Advice** General surface rust**Advice** Rear Exhaust has a minor leak of exhaust gases center (6.1.2 (a))**MOT #15** 2017-10-11 15:37**MOT test number** 847366982799**Result** ✓ Passed**Advice** General surface rust all over**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #14** 2017-10-11 09:13**MOT test number** 713244090983**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** General surface rust all over**MOT #13** 2016-10-26 13:19**MOT test number** 790027818550**Result** ✓ Passed**Advice** General surface rust all over**MOT #12** 2016-10-26 08:48**MOT test number** 571786195591**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** General surface rust all over**MOT #11** 2015-10-19 12:49**MOT test number** 221299088285**Result** ✓ Passed**MOT #10** 2014-10-27 09:20**MOT test number** 337520104342**Result** ✓ Passed**Notice** N/s/r tyre wall has a small cut but no cord

**MOT #9** 2013-10-28 12:25**MOT test number** 148911503361**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-10-16 10:57**MOT test number** 228780992210**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #7** 2011-10-18 09:30**MOT test number** 249531891237**Result** ✓ Passed**Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** O/s/r slighyt bind on wheel**MOT #6** 2010-10-26 10:14**MOT test number** 630639790256**Result** ✓ Passed**MOT #5** 2009-11-03 09:52**MOT test number** 510577809381**Result** ✓ Passed



MOT #4	2009-10-28 10:02
MOT test number	794271209313
Result	✗ Failed
Fail	Nearside Front Headlamp aim too low (1.8)
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

MOT #3	2008-10-21 11:37
MOT test number	690755498221
Result	✓ Passed

MOT #2	2007-10-29 09:12
MOT test number	903062507312
Result	✓ Passed

MOT #1	2006-10-20 10:16
MOT test number	713953896270
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-10-31
Last registration	2020-10-26
Complete history	See info



Registration #1	2001-10-31	9 mi
Registration #2	2006-10-20	23.137 mi
Registration #3	2007-10-29	24.879 mi
Registration #4	2008-10-21	26.016 mi
Registration #5	2009-10-28	27.517 mi
Registration #6	2009-11-03	27.553 mi
Registration #7	2010-10-26	28.193 mi
Registration #8	2011-10-18	28.966 mi
Registration #9	2012-10-16	30.122 mi
Registration #10	2013-10-28	31.175 mi
Registration #11	2014-10-27	32.299 mi
Registration #12	2015-10-27	33.377 mi
Registration #13	2016-10-27	34.455 mi
Registration #14	2017-10-27	35.533 mi
Registration #15	2018-10-27	36.611 mi
Registration #16	2019-10-27	37.689 mi
Registration #17	2020-10-27	38.767 mi
Registration #18	2021-10-27	39.845 mi
Registration #19	2022-10-27	40.923 mi
Registration #20	2023-10-27	42.001 mi
Registration #21	2024-10-27	43.079 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1690 mm
Height	1385 mm
Length	4290 mm
Wheel base	2465 mm
Kerb weight	1065 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	3ZZU147023