



report date: 2024-03-29

General information

| | |
|---------------------|-----------------|
| Make | VOLVO |
| Model | V50 D2 R-DESIGN |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 121 mph |
| 0 - 60 mph | 10.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 113 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 74.3 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 114 g/km |
| CO2 label | C |



**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-03-10 |
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 3 |

MOT #13 2024-03-05 14:55**MOT test number** 102612525488**Result** Passed**Next expiry date** 2025-03-10

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #12 2023-03-06 10:20**MOT test number** 935603879769**Result** Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2022-03-05 08:41**MOT test number** 681720849087**Result** Passed**MOT #10** 2021-03-11 11:33**MOT test number** 867088588473**Result** Passed

**MOT #9** 2020-02-18 09:41**MOT test number** 977026902125**Result** ✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #8 2019-03-05 17:21**MOT test number** 244949388975**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2018-03-02 15:31**MOT test number** 797281793911**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #6 2017-02-28 10:26**MOT test number** 693511283103**Result** ✓ Passed

**MOT #5** 2017-02-28 10:26**MOT test number** 509202922351**Result** ✗ Failed**Pass with rectification** Nearside Front Brake pipe inadequately clipped flexy (3.6.B.1)**MOT #4** 2016-01-15 10:25**MOT test number** 566138594825**Result** ✓ Passed**MOT #3** 2015-01-07 10:27**MOT test number** 645247105004**Result** ✓ Passed**MOT #2** 2015-01-07 10:27**MOT test number** 268517005039**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**MOT #1** 2014-01-20 15:21**MOT test number** 998440624097**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
10 March 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 10 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |   |
| Plate since | 2024-03-29 |
| Current registration |   |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2010-12-23 |
| Last registration | 2024-03-05 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-12-23 | 16 mi |
| Registration #2 | 2014-01-20 | 20.809 mi |
| Registration #3 | 2015-01-07 | 24.050 mi |
| Registration #4 | 2016-01-15 | 28.377 mi |
| Registration #5 | 2017-02-28 | 31.557 mi |
| Registration #6 | 2017-02-28 | 31.557 mi |
| Registration #7 | 2018-03-02 | 34.203 mi |
| Registration #8 | 2019-03-20 | 35.277 mi |
| Registration #9 | 2019-03-20 | 35.277 mi |
| Registration #10 | 2019-03-20 | 35.277 mi |
| Registration #11 | 2019-03-20 | 35.277 mi |
| Registration #12 | 2019-03-20 | 35.277 mi |
| Registration #13 | 2019-03-20 | 35.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4266 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1359 kg |
| Max. allowed weight | 1780 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1361361 |