



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history



Entry 2

Date	2023-11-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-12-16
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	14
Total items failed	8

MOT #14	2023-12-12 10:03
MOT test number	532710167758
Result	✓ Passed
Next expiry date	2024-12-11

MOT #13	2023-01-11 11:58
MOT test number	641735560128
Result	✓ Passed

MOT #12	2022-01-21 10:36
MOT test number	661708222949
Result	✓ Passed

MOT #11	2022-01-19 14:30
MOT test number	595017261677
Result	✗ Failed

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Shock absorbers has negligible damping effect (5.3.2 (d))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #10** 2020-10-02 13:48**MOT test number** 445674073738**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2019-09-27 10:51**MOT test number** 586858711483**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))**Advice** Rear Tyre worn close to legal limit/worn on edge Both sides. (5.2.3 (e))**MOT #8** 2018-09-29 08:31**MOT test number** 186213208207**Result** ✓ Passed**MOT #7** 2017-10-02 15:15**MOT test number** 399666803695**Result** ✓ Passed**Advice** Nearside and offside front tyre edges are worn**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)

**MOT #6** 2017-09-28 11:47**MOT test number** 355293464339**Result** ✗ Failed**Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Offside Headlamp aim too low (1.8)**Advice** Nearside and offside front tyre edges are worn**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Nearside Headlamp aim too low (1.8)**MOT #5** 2016-09-13 17:02**MOT test number** 865300210195**Result** ✓ Passed**MOT #4** 2016-09-13 08:59**MOT test number** 942156416860**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened on inner face (3.5.1i)**Fail** Rear brake disc in such a condition that it is seriously weakened on inner face (3.5.1i)**MOT #3** 2016-04-19 10:50**MOT test number** 522372835959**Result** ✓ Passed**Advice** Both front tyres worn on inner edge**MOT #2** 2016-03-04 17:07**MOT test number** 977456818344**Result** ✓ Passed



MOT #1	2015-03-11 12:02
MOT test number	508190475027
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Items removed from driver's view prior to test



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
11 December 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	11 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-03-23
Last registration	2023-12-12
Complete history	See info



Registration #1	2012-03-23	24 mi
Registration #2	2015-03-11	49.379 mi
Registration #3	2016-03-04	59.894 mi
Registration #4	2016-04-19	59.963 mi
Registration #5	2016-09-13	59.999 mi
Registration #6	2016-09-13	60.000 mi
Registration #7	2017-09-28	71.214 mi
Registration #8	2017-10-02	71.383 mi
Registration #9	2018-09-29	83.525 mi
Registration #10	2019-09-29	95.667 mi
Registration #11	2019-09-29	95.667 mi
Registration #12	2019-09-29	95.667 mi
Registration #13	2019-09-29	95.667 mi
Registration #14	2019-09-29	95.667 mi
Registration #15	2019-09-29	95.667 mi
Registration #16	2019-09-29	95.667 mi
Registration #17	2019-09-29	95.667 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719