



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Red
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-08-09
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-01
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	9
Total items failed	18

MOT #18	2024-02-02 12:34
MOT test number	221260710025
Result	✓ Passed
Next expiry date	2025-02-01

MOT #17	2023-01-25 11:41
MOT test number	246939984590
Result	✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2022-01-24 16:11
MOT test number	298564734141
Result	✓ Passed

**MOT #15** 2022-01-22 09:06**MOT test number** 927345893952**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt boot split (6.1.7 (g) (ii))**Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Fail** Rear Rear fog lamp not working (4.5.1 (a) (ii))**MOT #14** 2021-01-07 10:57**MOT test number** 673076387371**Result** ✓ Passed**MOT #13** 2021-01-06 14:42**MOT test number** 480805003165**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Pass with rectification** Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #12** 2020-01-31 11:21**MOT test number** 802282261157**Result** ✓ Passed**Advice** Oil leak, but not excessive sump corroded (8.4.1 (a) (i))**MOT #11** 2019-01-28 11:13**MOT test number** 551836006840**Result** ✓ Passed

**MOT #10** 2019-01-26 10:30**MOT test number** 288186226537**Result** ✗ Failed

**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure nsf tyre inner sidewall badly perished (5.2.3 (d) (ii))

**Fail** Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Fail** Offside Front Suspension arm pin or bush excessively worn osf lower arm rear bush badly worn (5.3.4 (a) (i))

**Fail** Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

**Fail** Nearside Rear Seat belt buckle not functioning as intended nsr belt buckle not releasing under pressure (7.1.2 (d))

**Fail** Nearside Front Suspension arm pin or bush excessively worn nsf lower arm rear bush baly worn (5.3.4 (a) (i))

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #9** 2018-01-20 11:13**MOT test number** 967657016131**Result** ✓ Passed**MOT #8** 2017-01-14 10:31**MOT test number** 252355132761**Result** ✓ Passed**MOT #7** 2015-12-30 11:07**MOT test number** 516964987065**Result** ✓ Passed**MOT #6** 2015-01-09 09:56**MOT test number** 278839605059**Result** ✓ Passed

**MOT #5** 2014-01-09 11:32**MOT test number** 898259204094**Result** ✓ Passed**MOT #4** 2014-01-09 11:32**MOT test number** 178109604480**Result** ✗ Failed**Pass with rectification** Offside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #3** 2013-01-14 11:43**MOT test number** 445584113030**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-01-18 13:51**MOT test number** 128108812489**Result** ✓ Passed**MOT #1** 2012-01-18 13:09**MOT test number** 425868012022**Result** ✗ Failed**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
1 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	1 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>NC58UKK</b>
Plate since	2019-09-28
Current registration	<b>NC58UKK</b>
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-01-21
Last registration	2024-02-02
Complete history	<a href="#">See info</a>



Registration #1	2009-01-21	29 mi
Registration #2	2012-01-18	13.933 mi
Registration #3	2012-01-18	13.933 mi
Registration #4	2013-01-14	15.802 mi
Registration #5	2014-01-09	22.066 mi
Registration #6	2015-01-09	25.137 mi
Registration #7	2015-12-30	27.357 mi
Registration #8	2017-01-14	30.201 mi
Registration #9	2018-01-20	32.081 mi
Registration #10	2019-01-26	34.450 mi
Registration #11	2020-01-26	35.333 mi
Registration #12	2021-01-26	36.216 mi
Registration #13	2022-01-26	37.099 mi
Registration #14	2023-01-26	37.982 mi
Registration #15	2024-01-26	38.865 mi
Registration #16	2025-01-26	39.748 mi
Registration #17	2026-01-26	40.631 mi
Registration #18	2027-01-26	41.514 mi
Registration #19	2028-01-26	42.397 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4HG8493714