



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2015
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-07-05
Pictures	17
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-23
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #8	2023-08-24 08:49
MOT test number	799490230971
Result	✓ Passed
Next expiry date	2024-08-23
Advice	Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2023-08-24 08:49**MOT test number** 789323065164**Result** ✗ Failed**Pass with rectification** Nearside Rear Lower Position lamp not working (4.2.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #6** 2022-08-24 07:48**MOT test number** 914410077964**Result** ✓ Passed**MOT #5** 2022-01-14 12:16**MOT test number** 692451864722**Result** ✓ Passed**MOT #4** 2021-01-11 15:59**MOT test number** 893778050003**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slight perish/cracking rear bush (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement slight perish/cracking rear bush (5.3.4 (a) (i))

**MOT #3** 2021-01-11 11:09**MOT test number** 292754590243**Result** ✗ Failed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slight perish/cracking rear bush (5.3.4 (a) (i))

Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement slight perish/cracking rear bush (5.3.4 (a) (i))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2019-07-12 15:36**MOT test number** 445266403286**Result** ✓ Passed**MOT #1** 2018-07-11 13:26**MOT test number** 628245420306**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-16
Last registration	2023-08-24
Complete history	See info



Registration #1	2015-07-16	20 mi
Registration #2	2018-07-11	6.310 mi
Registration #3	2019-07-12	7.068 mi
Registration #4	2021-01-11	7.948 mi
Registration #5	2021-01-11	7.948 mi
Registration #6	2023-08-24	7.948 mi
Registration #7	2023-08-24	7.948 mi
Registration #8	2023-08-24	7.948 mi
Registration #9	2023-08-24	7.948 mi
Registration #10	2023-08-24	7.948 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1643 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	37 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	1121042