





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | JETTA SE TDI |
| Colour | Silver |
| Year of manufacture | 2008 |
| Top speed | 128 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 140 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 2.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 48.7 mpg |
| CO2 emission | 148 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2023-11-23 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 7 |

| MOT #15 | 2022-11-16 13:24 |
|------------------|------------------|
| MOT test number | 363968478976 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-23 |

| MOT #14 | 2021-11-24 11:44 | |
|---|-----------------------|--|
| MOT test | t number 673895374156 | |
| Result | ✓ Passed | |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |

| MOT #13 | 2021-11-23 11:12 | |
|--|-------------------------|--|
| MOT test number | 942077771903 | |
| Result | X Failed | |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | | |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously wea | kened (1.1.14 (a) (ii)) | |

CarCheck.co.uk page 3/13



MOT #12 2020-11-23 10:19

MOT test number 602577887529

Result
✓ Passed

Advice Front brake discs corroded

Advice Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11 2019-10-28 17:07

MOT test number 306690784696

Result ✓ Passed

Advice Spare tyre defective spare tyre flat

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10 2019-10-25 09:26

MOT test number 365569971814

Result X Failed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Central Items removed from driver's view prior to test removed air freshener from drivers view

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Spare tyre defective spare tyre flat

Fail Offside Front Headlamp aim too high (4.1.2 (a))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Nearside Front Headlamp aim too high (4.1.2 (a))

Fail Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))

CarCheck.co.uk page 4/13



FV57XST

report date: 2024-03-29

| MOT #9 | | 2018-11-07 09:39 |
|---|--------|------------------|
| MOT test | number | 368049952730 |
| Result | | ✓ Passed |
| Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) | | |
| MOT #8 | | 2017-11-18 09:08 |
| MOT test | number | 485795717014 |
| Result | | ✓ Passed |

| MOT #7 | 2016-11-18 13:59 |
|-----------------|------------------|
| MOT test number | 716577321168 |
| Result | ✓ Passed |

| MOT #6 | 2015-11-18 14:03 |
|-----------------|------------------|
| MOT test number | 163606216508 |
| Result | ✓ Passed |

| MOT #5 | 2015-01-12 11:38 |
|-----------------|------------------|
| MOT test number | 196022015417 |
| Result | ✓ Passed |

| MOT #4 | 2013-12-12 15:57 |
|-----------------|------------------|
| MOT test number | 249376243316 |
| Result | ✓ Passed |

| MOT #3 | 2012-12-12 09:34 |
|-----------------|------------------|
| MOT test number | 295597042397 |
| Result | ✓ Passed |

CarCheck.co.uk page 5/13



MOT #2 2011-12-12 15:44

MOT test number 525236441349

MOT #1 2011-01-04 09:06

MOT test number 928344701091

Result
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 62 |
| MOT expiry date | 23 November 2023 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category


Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



| Owner history | |
|---|-----------------|
| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere. | |
| ********* | |
| | |
| *************************************** | |
| ********* | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | NE ZIS UK |
| Plate since | |
| | More info > |
| | |
| | |

CarCheck.co.uk page 10/13



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2008-01-01 |
| Last registration | 2022-11-16 |
| Complete history | See info |



| Registration #1 | 2008-01-01 | 17 mi |
|--|------------|---|
| Registration #2 | 2011-01-04 | 37.795 mi |
| Registration #3 | 2011-12-12 | 42.053 mi |
| Registration #4 | 2012-12-12 | 46.751 mi |
| Registration #5 | 2013-12-12 | 52.907 mi |
| Registration #6 | 2015-01-12 | 55.818 mi |
| Registration #7 | 2015-11-18 | 59.846 mi |
| Registration #8 | 2016-11-18 | 73.787 mi |
| Registration #9 | 2017-11-18 | 87.047 mi |
| | | |
| Registration #10 | | 11.777 es |
| | | 11.777 es |
| Registration #10 | | 11.777 es 11.777 es 11.777 es |
| Registration #10 Registration #11 | | 11.777-00 11.777-00 11.777-00 |
| Registration #10 Registration #11 Registration #12 | | 11.777-00 11.777-00 11.777-00 11.777-00 |
| Registration #10 Registration #11 Registration #12 Registration #13 | | 11 777 46 11 777 46 11 777 46 11 777 46 11 777 46 |
| Registration #10 Registration #11 Registration #12 Registration #13 Registration #14 | | 11 777 46 11 777 46 11 777 46 11 777 46 11 777 46 |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1781 mm |
|---------------------|---------|
| Height | 1459 mm |
| Length | 4554 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1556 kg |
| Max. allowed weight | 1990 kg |

Additional information

| Fuel tank capacity | 55 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| CarChaeleeaule | naga 12/11 |

CarCheck.co.uk page 13/13

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | BKD C38305 |