




report date: 2024-03-29

General information

Make	VOLVO
Model	S80 T SE
Colour	Silver
Year of manufacture	2008
Top speed	146 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 4.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	244 g/km
CO2 label	L



**MOT history**

MOT expiry date	2021-01-10
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #11	2020-01-08 09:42
MOT test number	775257406245
Result	✓ Passed
Next expiry date	2021-01-10

MOT #10	2019-01-11 12:19
MOT test number	344162785307
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9	2017-04-12 16:12
MOT test number	323421270541
Result	✓ Passed

MOT #8	2016-04-09 10:49
MOT test number	819628195638
Result	✓ Passed
Advice	Baby seat fitted to the nearside rear of car unable to check seat belt
Advice	Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #7** 2015-03-21 09:55**MOT test number** 505940885071**Result** ✓ Passed**MOT #6** 2014-04-14 16:19**MOT test number** 107384504138**Result** ✓ Passed**MOT #5** 2013-03-08 16:56**MOT test number** 139797263045**Result** ✓ Passed**MOT #4** 2012-03-21 14:55**MOT test number** 265681382027**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight damage to N/S/R Tyre sidewall**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2012-03-21 10:19**MOT test number** 859631782010**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Notice** Slight damage to N/S/R Tyre sidewall**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-04-19 16:43
MOT test number	967639801131
Result	✓ Passed

MOT #1	2011-04-19 13:59
MOT test number	985019601191
Result	✗ Failed

Fail Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



Tax & MOT check

X

Untaxed

Tax expired:
30 April 2021

X

MOT

Expired:
10 January 2021

Tax status	Expired at 30 April 2021
Days left	1096 days too late
MOT expiry date	10 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YR08NNO
Plate since	2019-03-29
Current registration	YR08NNO
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2008-04-19
Last registration	2020-01-08
Complete history	See info



Registration #1	2008-04-19	10 mi
Registration #2	2011-04-19	31.371 mi
Registration #3	2011-04-19	31.371 mi
Registration #4	2012-03-21	40.070 mi
Registration #5	2012-03-21	40.070 mi
Registration #6	2013-03-08	48.786 mi
Registration #7	2019-01-08	55.277 mi
Registration #8	2019-01-08	55.277 mi
Registration #9	2019-01-08	55.277 mi
Registration #10	2019-01-08	55.277 mi
Registration #11	2019-01-08	55.277 mi
Registration #12	2019-01-08	55.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2106 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1553 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Engine number	4044900
---------------	---------