



HYUNDAI

PFI7RRX


report date: 2024-03-28

General information

Make	HYUNDAI
Model	I20 MPI SE
Colour	Silver
Year of manufacture	2017
Top speed	106 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	122 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	68.9 mpg
Consumption combined	58.9 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-24
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #9	2023-07-26 10:55
--------	------------------

MOT test number	623181823154
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-27
------------------	------------

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tyre getting and worn on the inside edge (5.2.3 (e))
- Advice** Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre wearing on the inside edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre is very worn on the inside side and outside edges (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre perished and split between the tread (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inside face corroded (1.1.14 (a) (ii))

**MOT #8**

2023-07-26 09:13

MOT test number

207693740930

Result**✗ Failed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tyre getting and worn on the inside edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge tyre wearing on the inside edge (5.2.3 (e))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge tyre is very worn on the inside side and outside edges (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre perished and split between the tread (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inside face corroded (1.1.14 (a) (ii))

Advice Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #7

2022-07-25 11:38

MOT test number

454296162827

Result**✓ Passed**

Advice Engine oil on minimum and a black colour

Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened brake surface is corroded 50 % of the face (1.1.14 (a) (ii))

Advice Engine emissions poor hydro carbons high

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake fluid ready for changing

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6**

2022-07-25 11:05

MOT test number

260853494287

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Engine oil on minimum and a black colour
- Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened brake surface is corroded 50 % of the face (1.1.14 (a) (ii))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Engine emissions poor hydro carbons high
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Advice** Brake fluid ready for changing

MOT #5

2021-07-28 12:59

MOT test number

630251167230

Result**✓ Passed****MOT #4**

2021-05-13 08:57

MOT test number

580103710704

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3

2020-05-28 14:29

MOT test number

111981898169

Result**✓ Passed**

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #2** 2020-05-28 13:46**MOT test number** 470048035706**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2020-05-23 10:37**MOT test number** 889801086783**Result** ✓ Passed**Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	PF17RRX
Plate since	2019-09-28
Current registration	PF17RRX
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-05-31
Last registration	2023-07-26
Complete history	See info



Registration #1	2017-05-31	16 mi
Registration #2	2020-05-28	42.366 mi
Registration #3	2020-05-28	42.370 mi
Registration #4	2021-05-13	55.568 mi
Registration #5	2023-05-26	55.577 mi
Registration #6	2023-05-26	55.577 mi
Registration #7	2023-05-26	55.577 mi
Registration #8	2023-05-26	55.577 mi
Registration #9	2023-05-26	55.577 mi
Registration #10	2023-05-26	55.577 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	85%
Children	73%
Pedestrian	79%
Safety systems	64%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1734 mm
Height	1474 mm
Length	4035 mm
Wheel base	2570 mm
Kerb weight	1158 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LAGM263687