



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 HDI ALLURE
Colour	Blue
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	52.3 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2


Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-21
Pictures	9
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2023-07-28
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	32
Total items failed	0

MOT #11	2022-07-28 14:51
MOT test number	165631703781
Result	✓ Passed
Next expiry date	2023-07-28

MOT #10	2022-07-28 08:07
MOT test number	499476923623
Result	✗ Failed

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Undertray not fully secure (8.1.1 (b) (i))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm inside edge (5.2.3 (e))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9	2021-07-29 13:15
MOT test number	717624265905
Result	✓ Passed

**MOT #8** 2021-07-29 10:16**MOT test number** 519052581943**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Rear Road wheel fixing missing WHEEL NUT MISSING (5.2.1 (a) (i))**DANGEROUS** Nearside Front Passenger's seat insecure SEAT BASE WONT SECURE (6.2.6 (a) (ii))**MAJOR** Nearside Front Road wheel fixing missing WHEEL NUT MISSING (5.2.1 (a) (i))**MOT #7** 2020-10-08 14:46**MOT test number** 393942079471**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs corroded and worn on inner braking surface (1.1.14 (a) (ii))**Advice** Undertray fitted unable to fully inspect for leaks underneath**MOT #6** 2020-10-08 11:21**MOT test number** 374057087809**Result** ✗ Failed**DANGEROUS** Rear Brake disc in such a condition that it is seriously weakened both rear discs (1.1.14 (a) (ii))**Advice** Undertray fitted unable to fully inspect for leaks underneath**MAJOR** Rear Service brake excessively fluctuating (1.2.1 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front discs corroded and worn on inner braking surface (1.1.14 (a) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #5** 2019-10-15 11:39**MOT test number** 762745048436**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm worn on edges (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2018-10-09 09:39**MOT test number** 287258132156**Result** ✓ Passed**MOT #3** 2017-09-27 12:46**MOT test number** 900762575421**Result** ✓ Passed**Advice** Turbo blowing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Slight smearing from front wipers**Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped worn (3.5.1i)**Advice** Both front tyres wearing inner edges**MOT #2** 2016-10-04 09:11**MOT test number** 222751185227**Result** ✓ Passed



MOT #1	2015-10-23 09:14
MOT test number	485874839239
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
31 December 2022

✕
MOT

Expired:
28 July 2023

Tax status	Expired at 31 December 2022
Days left	485 days too late
MOT expiry date	28 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KN62WPW
Plate since	2019-03-28
Current registration	KN62WPW
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-24
Last registration	2022-07-28
Complete history	See info



Registration #1	2012-10-24	10 mi
Registration #2	2015-10-23	22.961 mi
Registration #3	2016-10-04	32.322 mi
Registration #4	2017-09-27	43.231 mi
Registration #5	2018-10-09	55.161 mi
Registration #6	2019-10-15	68.483 mi
Registration #7	2020-10-08	78.666 mi
Registration #8	2021-05-20	85.277 mi
Registration #9	2021-05-20	85.277 mi
Registration #10	2021-05-20	85.277 mi
Registration #11	2021-05-20	85.277 mi
Registration #12	2021-05-20	85.277 mi
Registration #13	2021-05-20	85.277 mi
Registration #14	2021-05-20	85.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	JBER3141583