



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-08-26
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-14
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	25
Total items failed	0

MOT #12	2024-03-14 15:18
MOT test number	293580643114
Result	✓ Passed
Next expiry date	2025-03-14
Advice	Offside Front Outer Tyre slightly damaged sidewall damage (5.2.3 (d) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))

MOT #11	2024-03-13 12:02
MOT test number	573235713394
Result	✗ Failed
DANGEROUS	Nearside Front Tyre has ply or cords exposed cords showing (5.2.3 (d) (ii))
Advice	Offside Front Outer Tyre slightly damaged sidewall damage (5.2.3 (d) (ii))
MAJOR	Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))
MAJOR	Front Windscreen washer not working (3.5 (a))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10** 2023-03-08 16:59**MOT test number** 155629789149**Result** ✓ Passed**Advice** Nearside Front Outer Tyre slightly damaged wall (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge wearing (5.2.3 (e))**MOT #9** 2023-03-07 11:05**MOT test number** 841216378174**Result** ✗ Failed**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge wearing (5.2.3 (e))**MAJOR** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Outer Tyre slightly damaged wall (5.2.3 (d) (ii))**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #8** 2022-03-15 12:02**MOT test number** 218029029999**Result** ✓ Passed**MOT #7** 2021-09-25 09:56**MOT test number** 675578992228**Result** ✓ Passed**Advice** Dsm cant detect any smoke

**MOT #6** 2020-09-10 19:35**MOT test number** 575475319882**Result** ✓ Passed**MOT #5** 2019-09-11 17:18**MOT test number** 246499775966**Result** ✓ Passed**Advice** Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-09-12 14:21**MOT test number** 881744727811**Result** ✓ Passed**MOT #3** 2017-09-13 17:55**MOT test number** 366518994313**Result** ✓ Passed**Advice** Front Brake pad(s) modified but not seriously weakened (3.5.1n)**Advice** Rear Brake pad(s) modified but not seriously weakened (3.5.1n)**MOT #2** 2016-09-08 17:33**MOT test number** 584922691684**Result** ✓ Passed**MOT #1** 2015-08-27 13:37**MOT test number** 115416210456**Result** ✓ Passed**Advice** Both front tyres wearing on extreme inner edges**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
29 February 2024

✓

MOT

Expires:
14 March 2025

Tax status	Expired at 29 February 2024
Days left	60 days too late
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-14
Last registration	2024-03-14
Complete history	See info



Registration #1	2012-09-14	19 mi
Registration #2	2015-08-27	39.021 mi
Registration #3	2016-09-08	50.355 mi
Registration #4	2017-09-13	60.231 mi
Registration #5	2018-09-12	68.926 mi
Registration #6	2019-09-11	78.322 mi
Registration #7	2020-09-10	85.335 mi
Registration #8	2021-09-09	92.348 mi
Registration #9	2022-09-08	99.361 mi
Registration #10	2023-09-07	106.374 mi
Registration #11	2024-03-14	113.387 mi
Registration #12	2024-03-14	113.387 mi
Registration #13	2024-03-14	113.387 mi
Registration #14	2024-03-14	113.387 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	2259719