



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 GDI SE NAV BLUE DRIVE
Colour	White
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.800 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F








Internet history

Entry 1

Date	2022-02-12
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-08
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	6
Total items failed	6

MOT #10	2024-02-09 17:10
MOT test number	295456995716
Result	✓ Passed
Next expiry date	2025-02-08

MOT #9	2024-02-09 09:30
MOT test number	222106657155
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened offside and nearside (1.1.14 (a) (ii))
Fail	Rear Service brake excessively fluctuating (1.2.1 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #8	2023-03-20 16:51
MOT test number	959621038777
Result	✓ Passed
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #7** 2023-03-13 16:54**MOT test number** 808982578247**Result** ✗ Failed**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #6** 2022-03-01 07:51**MOT test number** 877577675258**Result** ✓ Passed**MOT #5** 2021-03-18 09:00**MOT test number** 497739815337**Result** ✓ Passed**MOT #4** 2021-03-17 17:13**MOT test number** 428831169624**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Fail** Front Service brake excessively fluctuating (1.2.1 (e))**MOT #3** 2020-03-09 15:59**MOT test number** 441562611103**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #2	2019-01-29 12:00
MOT test number	221691346538
Result	✓ Passed

MOT #1	2018-06-04 09:52
MOT test number	658177781655
Result	✓ Passed

Advice Offside Rear Nail in tyre



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	8 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-06-24
Last registration	2024-02-09
Complete history	See info



Registration #1	2015-06-24	7 mi
Registration #2	2018-06-04	10.814 mi
Registration #3	2019-01-29	12.416 mi
Registration #4	2020-03-09	17.214 mi
Registration #5	2021-03-17	20.212 mi
Registration #6	2021-03-18	20.212 mi
Registration #7	2022-03-29	20.212 mi
Registration #8	2022-03-29	20.212 mi
Registration #9	2022-03-29	20.212 mi
Registration #10	2022-03-29	20.212 mi
Registration #11	2022-03-29	20.212 mi
Registration #12	2022-03-29	20.212 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

G4FDFZ518175