




report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L1H1 2700 CDTI ECOFLEX S/S
Colour	Silver
Year of manufacture	2017
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	260 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-19
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #6	2023-10-06 14:02
MOT test number	135277039830
Result	✓ Passed
Next expiry date	2024-10-08

MOT #5	2022-10-01 09:52
MOT test number	719257027363
Result	✓ Passed

MOT #4	2021-10-07 10:44
MOT test number	958519636839
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2021-10-04 13:31**MOT test number** 761866249913**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2020-09-23 15:11**MOT test number** 622276149841**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #1** 2020-09-22 06:48**MOT test number** 888395061758**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
8 October 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BF67ABU
Plate since	2019-03-28
Current registration	 BF67ABU
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-10-09
Last registration	2023-10-06
Complete history	See info



Registration #1	2017-10-09	8 mi
Registration #2	2020-09-22	54.341 mi
Registration #3	2020-09-23	54.341 mi
Registration #4	2021-10-04	65.861 mi
Registration #5	2022-09-22	75.277 mi
Registration #6	2022-09-22	75.277 mi
Registration #7	2022-09-22	75.277 mi
Registration #8	2023-10-06	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1725 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MJ - C012652LWX