



report date: 2024-03-29

General information

Make	MAZDA
Model	2 TAMURA
Colour	Silver
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-21
Pictures	18
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-07-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	36
Total items failed	9

MOT #13	2023-07-04 10:21
---------	------------------

MOT test number	749946459120
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-07
------------------	------------

- AdviceNearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- AdviceOffside Drag link end ball joint has slight play (2.1.3 (b) (i))
- AdviceCovers fitted to outer sills
- AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt
- AdviceSteering feels knochy no fault found
- AdviceFront Brake disc worn, but not excessively (1.1.14 (a) (i))
- AdviceOffside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- AdviceUnderneath covers fitted
- AdviceO/s/r light cluster damaged
- AdviceOffside Rear Nail in tyre & inner edge wearing

**MOT #12**

2022-07-08 14:28

**MOT test number**

122218958987

**Result**

✓ Passed

- Advice** Points of corrosion appearing to underside of vehicle
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Underneath covers fitted
- Advice** O/s/r light cluster damaged
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Covers fitted to outer sills

**MOT #11**

2022-07-08 11:14

**MOT test number**

659382162664

**Result**

✗ Failed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Underneath covers fitted
- Advice** O/s/r light cluster damaged
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Covers fitted to outer sills
- Advice** Points of corrosion appearing to underside of vehicle
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10**

2021-06-28 14:20

**MOT test number**

322279979783

**Result**

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Underneath covers fitted

**MOT #9** 2021-06-28 11:10**MOT test number** 826779515062**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing & inner edge wearing low & uneven wear (5.2.3 (d) (ii))**Advice** Underneath covers fitted**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing & inner edge wearing low & uneven wear (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**MOT #8** 2020-07-08 10:20**MOT test number** 553402251984**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**MOT #7** 2019-06-19 13:58**MOT test number** 673958748526**Result** ✓ Passed**MOT #6** 2019-06-19 13:58**MOT test number** 589829004777**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Front Direction indicator not working (4.4.1 (a) (ii))**Pass with rectification** Offside Headlamp not working on main beam (4.1.1 (a) (ii))

**MOT #5** 2018-04-04 10:16**MOT test number** 651254654909**Result** ✓ Passed

- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #4** 2018-04-03 11:30**MOT test number** 712494444878**Result** ✗ Failed

- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2017-03-17 09:47**MOT test number** 632096902296**Result** ✓ Passed**MOT #2** 2016-03-17 11:31**MOT test number** 131128488798**Result** ✓ Passed**MOT #1** 2015-02-02 13:52**MOT test number** 395813635072**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 July 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	7 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-31
Last registration	2023-07-04
Complete history	<a href="#">See info</a>



Registration #1	2012-03-31	18 mi
Registration #2	2015-02-02	7.953 mi
Registration #3	2016-03-17	11.378 mi
Registration #4	2017-03-17	14.370 mi
Registration #5	2018-04-03	20.787 mi
Registration #6	2018-04-04	20.791 mi
Registration #7	2019-06-19	25.279 mi
Registration #8	2019-06-19	25.279 mi
Registration #9	2019-06-19	25.279 mi
Registration #10	2019-06-19	25.279 mi
Registration #11	2019-06-19	25.279 mi
Registration #12	2019-06-19	25.279 mi
Registration #13	2019-06-19	25.279 mi
Registration #14	2019-06-19	25.279 mi
Registration #15	2019-06-19	25.279 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ A50824