



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO E4
Colour	Silver
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K






Internet history

Entry 2

Date	2023-05-24
Pictures	4
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-10-01
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-27
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	17
Total items failed	7

MOT #21	2023-10-28 10:05
MOT test number	659142794852
Result	✓ Passed
Next expiry date	2024-10-27

MOT #20	2023-10-28 10:05
MOT test number	146433348916
Result	✗ Failed
Pass with rectification Offside Front Direction indicator not working (4.4.1 (a) (ii))	

MOT #19	2022-09-29 11:05
MOT test number	953395234050
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (ii))
Advice	Offside Rear Nail in tyre
Minor	Front Headlamp lens slightly defective both sides (4.1.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge also perishing (5.2.3 (e))
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18** 2021-10-05 07:33**MOT test number** 925952626730**Result** ✓ Passed**MOT #17** 2021-10-05 07:33**MOT test number** 814403931360**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #16** 2021-03-17 13:00**MOT test number** 324851201387**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #15** 2020-01-22 14:26**MOT test number** 804775778450**Result** ✓ Passed**MOT #14** 2020-01-21 15:56**MOT test number** 502940322500**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #13** 2019-01-14 16:44**MOT test number** 545817040457**Result** ✓ Passed

**MOT #12** 2018-01-22 13:03**MOT test number** 321212261127**Result** ✓ Passed**MOT #11** 2018-01-22 09:19**MOT test number** 824097467939**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)**MOT #10** 2017-01-11 09:07**MOT test number** 229889453655**Result** ✓ Passed**Advice** Installation of child seats prevent a full inspection of rear adult seat belts**MOT #9** 2016-01-14 10:54**MOT test number** 892898640635**Result** ✓ Passed**MOT #8** 2015-01-20 09:22**MOT test number** 159320425492**Result** ✓ Passed

**MOT #7** 2014-01-07 15:37**MOT test number** 366037004047**Result** ✓ Passed**Notice** Nearside front tyre bald outside edge**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2013-01-14 16:23**MOT test number** 347304513080**Result** ✓ Passed**Notice** Nearside front tyre starting to wear outside edge**MOT #5** 2012-01-17 15:31**MOT test number** 969057012081**Result** ✓ Passed**MOT #4** 2012-01-16 15:40**MOT test number** 777606212004**Result** ✗ Failed**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #3** 2011-01-11 15:25**MOT test number** 797361111088**Result** ✓ Passed**MOT #2** 2010-01-18 09:09**MOT test number** 242178910068**Result** ✓ Passed**Notice** All tyre outer sidewalls starting to perish



MOT #1	2009-01-13 09:13
MOT test number	190423919488
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
27 October 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	27 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-01-31
Last registration	2023-10-28
Complete history	See info



Registration #1	2006-01-31	17 mi
Registration #2	2009-01-13	11.106 mi
Registration #3	2010-01-18	13.390 mi
Registration #4	2011-01-11	15.844 mi
Registration #5	2012-01-16	18.138 mi
Registration #6	2012-01-17	18.139 mi
Registration #7	2013-01-14	19.793 mi
Registration #8	2014-01-07	21.144 mi
Registration #9	2015-01-20	22.394 mi
Registration #10	2016-01-14	23.231 mi
Registration #11	2017-01-11	23.572 mi
Registration #12	2018-01-22	23.875 mi
Registration #13	2019-01-20	25.277 mi
Registration #14	2019-01-20	25.277 mi
Registration #15	2019-01-20	25.277 mi
Registration #16	2019-01-20	25.277 mi
Registration #17	2019-01-20	25.277 mi
Registration #18	2019-01-20	25.277 mi
Registration #19	2019-01-20	25.277 mi
Registration #20	2019-01-20	25.277 mi
Registration #21	2019-01-20	25.277 mi
Registration #22	2019-01-20	25.277 mi
Registration #23	2019-01-20	25.277 mi
Registration #24	2019-01-20	25.277 mi

More info >



Safety ratings

NCAP rating

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1454817