





### General information

Make	NISSAN
Model	MICRA VISIA
Colour	Silver
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С







### Internet history

Entry	1
Date	

Pictures

2021-06-11

98

Listing price

View report



source: yesauto.com



### MOT history

MOT expiry date	2024-06-27
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #11	2023-06-28 09:50
MOT test number	466598943101
Result	🗸 Passed
Next expiry date	2024-06-27
Advice Rear Brake pipe corroded, covered in grease or other material Nearside & C (1.1.11 (c))	Offside (Front to rear)
Advice Rear Brake pipe corroded, covered in grease or other material Nearside & C	Offside (1.1.11 (c))

MOT #10	2022-06-22 13:13
MOT test number	606462689843
Result	✓ Passed
<b>Advice</b> Offside Brake pipe corroded, covered in grease or other mater (1.1.11 (c))	rial front to rear to brake flexi

МОТ #9	2022-06-22 08:19	
MOT test number	946059344310	
Result	🗙 Failed	
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))		
Advice Offside Brake pipe corroded, covered in grease or other material front to rear to brake flexi (1.1.11 (c))		
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))		
Advice Center heat shield loose		





MOT #8	2021-06-28 13:38
MOT test number	490102797577
Result	✓ Passed
MOT #7	2021-06-28 09:26
MOT test number	158180394722
Result	🗙 Failed
Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its str	ructure (5.2.3 (d) (ii))
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2021-02-23 10:34
MOT test number	349375940930
Result	✓ Passed

MOT #5	2020-02-12 14:04
MOT test number	279387926416
Result	✓ Passed

MOT #4		2019-02-15 12:31
MOT test	number	190590620121
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (	a) (ii))

MOT #3	2018-03-12 14:56
MOT test number	941972804831
Result	✓ Passed





MOT #2	2017-12-06 11:21
MOT test number	153074093156
Result	Passed
Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not result movement (2.4.G.2)	ting in excessive
Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resultin movement (2.4.G.2)	ng in excessive
MOT #1	2017-02-07 12:24
MOT test number	996093377892
Result	Passed
<b>Advice</b> Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	



DU14ZWN report date: 2024-03-29

### Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 27 June 2024
Tax status	Valid until 1 June
Days left	32
MOT expiry date	27 June 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

#### Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this NISSAN had different number plates	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-30
Last registration	2023-06-28
Complete history	See info



Registration #1	2014-04-30	11 mi
Registration #2	2017-02-07	7.703 mi
Registration #3	2017-12-06	9.996 mi
Registration #4	2018-03-12	10.348 mi
Registration #5	2019-02-15	14.271 mi
Registration #6	2020-02-12	19.300 mi
Registration #7	2021-02-23	24.383 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.277 esi





### Car features

S0225	Air conditioning
\$0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg
Additional information	
Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12