



report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 DDIS
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-12
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	7
Total items failed	1

MOT #13	2023-05-10 09:05
MOT test number	607919224811
Result	✓ Passed
Next expiry date	2024-05-12

MOT #12	2022-05-11 14:47
MOT test number	497562621000
Result	✓ Passed

MOT #11	2022-05-09 10:46
MOT test number	698019308950
Result	✗ Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #10	2021-05-13 13:09
MOT test number	697119610088
Result	✓ Passed

MOT #9	2020-04-21 09:23
MOT test number	409952469093
Result	✓ Passed

**MOT #8** 2019-04-16 10:40**MOT test number** 372324032725**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #7** 2018-05-01 08:42**MOT test number** 320260666834**Result** ✓ Passed**MOT #6** 2017-04-05 11:10**MOT test number** 817497840356**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-04-05 13:24**MOT test number** 770238013247**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2015-04-30 16:26**MOT test number** 348600825110**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #3	2014-04-30 15:29
MOT test number	738230724121
Result	✓ Passed
MOT #2	2013-04-30 15:50
MOT test number	689930023187
Result	✓ Passed
MOT #1	2012-04-28 09:23
MOT test number	795529012161
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 May 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-06-30
Last registration	2023-05-10
Complete history	See info



Registration #1	2009-06-30	7 mi
Registration #2	2012-04-28	24.207 mi
Registration #3	2013-04-30	34.111 mi
Registration #4	2014-04-30	44.240 mi
Registration #5	2015-04-30	51.371 mi
Registration #6	2016-04-05	57.842 mi
Registration #7	2017-04-05	63.585 mi
Registration #8	2018-05-10	68.207 mi
Registration #9	2019-05-10	72.842 mi
Registration #10	2020-05-10	77.467 mi
Registration #11	2021-05-10	82.092 mi
Registration #12	2022-05-10	86.717 mi
Registration #13	2023-05-10	91.342 mi
Registration #14	2024-03-28	95.967 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1300 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	10JBAX0005790