



report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC TDCI
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-23
Pictures	3
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-19
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #16	2023-08-18 15:46
MOT test number	317365023079
Result	✓ Passed
Next expiry date	2024-08-19
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15	2023-08-18 11:08
MOT test number	519639168703
Result	✗ Failed
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Windscreen washer not working (3.5 (a))

MOT #14	2022-08-19 14:41
MOT test number	895144100400
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2022-08-19 12:12**MOT test number** 564596078804**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #12** 2021-08-06 08:15**MOT test number** 815234489365**Result** ✓ Passed**MOT #11** 2020-08-20 10:14**MOT test number** 601631352803**Result** ✓ Passed**MOT #10** 2019-01-04 15:04**MOT test number** 992187842635**Result** ✓ Passed**MOT #9** 2018-01-22 13:34**MOT test number** 654954745126**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
lower arm rear bush (2.4.G.2)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement  
lower arm rear bush (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit inner worn, advise to replace (4.1.E.1)

**MOT #8**

2017-01-13 15:38

**MOT test number**

576531617029

**Result**

✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit wearing inner (4.1.E.1)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Nearside Front Tyre worn close to the legal limit wearing inner (4.1.E.1)

**MOT #7**

2017-01-13 14:43

**MOT test number**

695526715866

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit wearing inner (4.1.E.1)

**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Offside Front Tyre worn close to the legal limit wearing inner (4.1.E.1)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**MOT #6**

2016-01-04 15:05

**MOT test number**

870281106469

**Result**

✓ Passed

**MOT #5**

2015-01-19 11:26

**MOT test number**

309639215086

**Result**

✓ Passed

**Notice** Offside front and nearside rear tyres de-void of tread inner edges

**MOT #4** 2015-01-19 11:26**MOT test number** 528569215045**Result** ✗ Failed**Notice** Offside front and nearside rear tyres de-void of tread inner edges**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #3** 2014-01-29 17:14**MOT test number** 395529224052**Result** ✓ Passed**MOT #2** 2013-03-12 14:09**MOT test number** 127701573449**Result** ✓ Passed**MOT #1** 2012-03-19 14:12**MOT test number** 708809272096**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
19 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	19 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA09 MKX
Plate since	2019-03-28
Current registration	EA09 MKX
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-18
Last registration	2023-08-18
Complete history	<a href="#">See info</a>



Registration #1	2009-05-18	29 mi
Registration #2	2012-03-19	26.511 mi
Registration #3	2013-03-12	38.477 mi
Registration #4	2014-01-29	47.945 mi
Registration #5	2015-01-19	57.571 mi
Registration #6	2016-01-04	65.882 mi
Registration #7	2017-01-13	73.740 mi
Registration #8	2017-01-13	73.745 mi
Registration #9	2018-01-22	80.784 mi
Registration #10	2019-05-20	85.377 mi
Registration #11	2019-05-20	85.377 mi
Registration #12	2019-05-20	85.377 mi
Registration #13	2019-05-20	85.377 mi
Registration #14	2019-05-20	85.377 mi
Registration #15	2019-05-20	85.377 mi
Registration #16	2019-05-20	85.377 mi
Registration #17	2019-05-20	85.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

9C73512