




report date: 2024-03-28

General information

Make	VOLVO
Model	V60 D4 R-DESIGN NAV
Colour	White
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	56.5 mpg
Consumption extra urban	74.3 mpg
Consumption combined	67.3 mpg
CO2 emission	112 g/km
CO2 label	C






Internet history

Entry 2

Date	2023-12-06
Pictures	9
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-22
Pictures	41
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-04
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	6

MOT #9	2023-12-05 11:48
MOT test number	200781382436
Result	✓ Passed
Next expiry date	2024-12-04
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edge (5.2.3 (e))

MOT #8	2023-02-20 11:24
MOT test number	721967949248
Result	✓ Passed

MOT #7	2022-03-18 11:32
MOT test number	528958317990
Result	✓ Passed
Advice	Front both top mounts slightly noisy

MOT #6	2021-02-08 16:36
MOT test number	111378560189
Result	✓ Passed

**MOT #5** 2021-02-08 10:34**MOT test number** 724563090543**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively flat (3.4 (b) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Windscreen wiper does not clear the windscreen effectively flat (3.4 (b) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #4** 2020-02-18 10:14**MOT test number** 593751455808**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge wear (5.2.3 (e))**MOT #3** 2019-03-04 12:15**MOT test number** 346156580563**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear tyre badly worn on inside edge and about to expose cords**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #2** 2018-03-02 13:05**MOT test number** 127748092701**Result** ✓ Passed**Advice** Under trays & covers obscuring some components



MOT #1	2018-03-01 13:07
MOT test number	154325654825
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm Michelin pilot sport 3 235/40/18 95w (4.1.E.1)
Advice	Under trays & covers obscuring some components
Fail	Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 December 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	4 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-03-02
Last registration	2023-12-05
Complete history	See info



Registration #1	2015-03-02	22 mi
Registration #2	2018-03-01	74.761 mi
Registration #3	2018-03-02	74.761 mi
Registration #4	2019-03-04	85.528 mi
Registration #5	2020-02-18	95.828 mi
Registration #6	2021-02-08	102.908 mi
Registration #7	2023-12-05	102.908 mi
Registration #8	2023-12-05	102.908 mi
Registration #9	2023-12-05	102.908 mi
Registration #10	2023-12-05	102.908 mi
Registration #11	2023-12-05	102.908 mi
Registration #12	2023-12-05	102.908 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1662 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

1192817