





report date: 2024-03-28

#### General information

Make	MERCEDES-BENZ
Model	GLA GLA 220 D 4MATIC AMG LINE
Colour	White
Year of manufacture	2016
Top speed	135 mph
0 - 100 km/h	7.7 seconds
0 - 60 mph	7.7 seconds
Gearbox	7 speed automatic

#### Engine & fuel consumption

Power	130 kW / 177 HP / 174 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

### Internet history

#### Entry 3

Date 2021-09-24

Pictures 25

Listing price <u>View report</u>









source: yesauto.com


Entry 2

Date 2021-09-19

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-18


Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2025-01-04
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #8		2024-01-05 09:34
MOT test	number	442399730344
Result		✓ Passed
Next exp	iry date	2025-01-04
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not function	ioning (4.2.1 (a) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e))		
Advice Nearside Rear Brake pad(s) wearing thin worn uneven with otherside (1.1.13 (a) (ii))		
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)	)

MOT #7	2024-01-04 15:08
MOT test number	362185984138
Result	<b>×</b> Failed
Fail Front Windscreen washer provides insufficient washer liquid are full of water, s (a))	uspect blocked (3.5
Advice Nearside Rear Brake pad(s) wearing thin worn uneven with otherside (1.1.1	3 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Minor Offside Rear Position lamp with a multiple light source up to 1/2 not function	ing (4.2.1 (a) (i))
Advice Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm (5.2.3 (e)	))
Advice Engine oil low	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #6

MOT test number

273204967765

Result

Advice Nearside Front Tyre slightly damaged chunk out of sidewall, not exposing cords (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre

MOT #5 2021-09-20 07:41 **MOT** test number 896804771978 Result ✓ Passed MOT #4 2021-09-20 07:41 707861805682 **MOT test number** Result × Failed **Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3	2021-01-21 10:24
MOT test number	187585836298
Result	✓ Passed
MOT #2	2020-02-24 09:20
MOT test number	413692857379
Result	✓ Passed
MOT #1	2019-02-26 16:19
MOT test number	215978225799
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



#### Extra MERCEDES-BENZ salvage check



**Category** 

**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

### Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report <a href="https://example.com/here">here</a> .	
***************************************	
THE STATE OF THE S	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-02-26
Last registration	2024-01-05
Complete history	See info



Registration #1	2016-02-26	24 mi
Registration #2	2019-02-26	22.935 mi
Registration #3	2020-02-24	36.995 mi
Registration #4	2021-01-21	48.590 mi
Registration #5		11.777 es
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 ea
Registration #9		11.777 mi
Registration #10		11.777 ea
Registration #11		11.777 ea
Registration #12		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

#### Car features

S0225	Air conditionir
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

## Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	1804 mm
Height	1494 mm
Length	4417 mm
Wheel base	2699 mm
Kerb weight	1595 kg
Max. allowed weight	2075 kg

## Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	5
CarChock co.uk	page 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	65193033688471