



PEUGEOT

LT560FR

report date: 2024-03-29

General information

Make	PEUGEOT
Model	EXPERT 815 1.9D P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	125 Nm at 2.500 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

<b>MOT #17</b>	2020-11-16 14:35
<b>MOT test number</b>	893599805345
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-12-11
<b>Advice</b>	Offside Front Play in steering rack inner joint(s)
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

<b>MOT #16</b>	2020-11-16 14:35
<b>MOT test number</b>	682636609534
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Front Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Offside Front Play in steering rack inner joint(s)

**MOT #15**

2019-12-07 11:12

**MOT test number**

872548116334

**Result**

✓ Passed

- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Front subframe has slight surface rust
- Advice** Front Brake pedal wearing smooth (1.1.2 (c))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front to rear brake lines covered heavily with sealant
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Underbody has slight surface rust
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))
- Advice** Front to rear fuel lines covered heavily with sealant
- Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Parking brake efficiency just met the system may require adjustment or repair
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #14** 2018-11-21 09:47**MOT test number** 641241362861**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Coil spring corroded All coils front and rear (5.3.1 (b) (i))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Both near side and off side outer sills (6.1.1 (c) (i))**MOT #13** 2018-11-17 13:54**MOT test number** 723908364064**Result** ✗ Failed**Advice** Coil spring corroded All coils front and rear (5.3.1 (b) (i))**MAJOR** Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Near side and off side outer sills (6.1.1 (c) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Tyre tread depth below requirements of 1.6mm Near side front (5.2.3 (e))**MOT #12** 2017-11-23 11:08**MOT test number** 435690202030**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Brake load sensing valve stiff (3.6.E.3)**MOT #11** 2016-11-21 15:25**MOT test number** 845482864669**Result** ✓ Passed**MOT #10** 2015-11-24 11:56**MOT test number** 812355769604**Result** ✓ Passed

**MOT #9** 2014-11-17 12:43**MOT test number** 247121624371**Result** ✓ Passed**MOT #8** 2013-12-09 10:39**MOT test number** 555323043343**Result** ✓ Passed**Advice** Brake load sensing valve linkage stiff (3.6.E.3)**Notice** Handbrake loose on mountings**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Play in steering rack inner joint(s)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Oil leak**MOT #7** 2012-12-12 14:31**MOT test number** 889377042374**Result** ✓ Passed**MOT #6** 2012-12-12 10:08**MOT test number** 409647642392**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #5** 2011-10-07 14:30**MOT test number** 506620081266**Result** ✓ Passed

**MOT #4** 2011-09-28 16:01**MOT test number** 727051771287**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #3** 2010-09-03 14:50**MOT test number** 962486340240**Result** ✓ Passed**MOT #2** 2009-09-23 11:27**MOT test number** 461786169233**Result** ✓ Passed**MOT #1** 2009-09-22 15:28**MOT test number** 760775769260**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-09-05
Last registration	2020-11-16
Complete history	<a href="#">See info</a>



Registration #1	2006-09-05	27 mi
Registration #2	2009-09-22	41.832 mi
Registration #3	2009-09-23	41.850 mi
Registration #4	2010-09-03	55.732 mi
Registration #5	2011-09-28	68.977 mi
Registration #6	2011-10-07	69.231 mi
Registration #7	2012-12-12	88.712 mi
Registration #8	2012-12-12	88.712 mi
Registration #9	2013-05-20	95.377 mi
Registration #10	2013-05-20	95.377 mi
Registration #11	2013-05-20	95.377 mi
Registration #12	2013-05-20	95.377 mi
Registration #13	2013-05-20	95.377 mi
Registration #14	2013-05-20	95.377 mi
Registration #15	2013-05-20	95.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2130 mm
Length	4522 mm

Additional information

Fuel tank capacity	80 l
Fuel delivery	Indirect Injection
Number of doors	3
Number of seats	3
Engine number	DXFP6047121