



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Silver
Year of manufacture	2009
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.9 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-10
Pictures	31
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-21
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	18
Total items failed	7

MOT #16 2023-06-30 15:30

MOT test number 384299465884

Result ✓ Passed

Next expiry date 2024-07-21

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Coil spring corroded both (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15 2023-06-30 10:13

MOT test number 402393501360

Result ✗ Failed

Advice Rear Coil spring corroded both (5.3.1 (b) (i))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2022-07-22 13:41

MOT test number

376832517020

Result

✓ Passed

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear rear components corroded**Advice** Front front components corroded**MOT #13**

2022-07-20 17:05

MOT test number

752581827957

Result

✗ Failed

Advice Rear rear components corroded**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front front components corroded**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #12**

2021-09-18 14:37

MOT test number

970191980738

Result

✓ Passed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2021-09-17 11:33

MOT test number

587867019391

Result

✗ Failed

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))

**MOT #10** 2020-11-25 15:33**MOT test number** 981902122976**Result** ✓ Passed**MOT #9** 2020-03-19 12:15**MOT test number** 279826331162**Result** ✓ Passed**Advice** Centre rear heat shield insecure slightly**Advice** Nearside Rear Nail in tyre in shoulder**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #8** 2019-03-15 08:44**MOT test number** 378981368054**Result** ✓ Passed**MOT #7** 2018-03-14 09:23**MOT test number** 645744381981**Result** ✓ Passed**MOT #6** 2017-03-27 09:00**MOT test number** 595792812204**Result** ✓ Passed**MOT #5** 2016-03-23 10:06**MOT test number** 334802895130**Result** ✓ Passed**MOT #4** 2015-03-25 10:01**MOT test number** 248644085014**Result** ✓ Passed



MOT #3	2014-03-21 10:35
MOT test number	949210384042
Result	✓ Passed
MOT #2	2013-03-25 10:43
MOT test number	475764083086
Result	✓ Passed
MOT #1	2012-04-05 16:52
MOT test number	216806792016
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
21 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-01
Last registration	2023-06-30
Complete history	See info



Registration #1	2009-09-01	21 mi
Registration #2	2012-04-05	29.490 mi
Registration #3	2013-03-25	37.598 mi
Registration #4	2014-03-21	45.154 mi
Registration #5	2015-03-25	50.614 mi
Registration #6	2016-03-23	57.451 mi
Registration #7	2017-03-27	62.748 mi
Registration #8	2018-03-14	69.229 mi
Registration #9	2019-03-15	76.120 mi
Registration #10	2020-03-20	83.377 mi
Registration #11	2021-03-20	90.377 mi
Registration #12	2022-03-20	97.377 mi
Registration #13	2023-03-20	104.377 mi
Registration #14	2024-03-20	111.377 mi
Registration #15	2025-03-20	118.377 mi
Registration #16	2026-03-20	125.377 mi
Registration #17	2027-03-20	132.377 mi
Registration #18	2028-03-20	139.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Kerb weight	1414 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	R20A31109240