



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC GRAND DYNAMIQUE TOMTOM DCI FAP
Colour	Blue
Year of manufacture	2011
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption



Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1	
Date	2021-06-13
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-04
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	21
Total items failed	12

MOT #15	2023-06-17 08:50
MOT test number	388138242957
Result	✓ Passed
Next expiry date	2024-07-04
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2022-06-08 12:49
MOT test number	275035554248
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2022-06-08 09:53

**MOT test number**

440754247403

**Result****✗ Failed****Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12**

2021-07-05 10:12

**MOT test number**

699611071615

**Result****✓ Passed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11**

2021-07-05 09:39

**MOT test number**

539631349661

**Result****✗ Failed****Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**MOT #10**

2021-07-01 09:19

**MOT test number**

729215403234

**Result****✗ Failed****Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Electronic braking system warning device indicates a fault (1.7 (b))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

**MOT #9** 2020-09-11 09:46**MOT test number** 750381923569**Result** ✓ Passed**MOT #8** 2019-09-06 16:11**MOT test number** 615795117329**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Seat belt webbing slightly damaged or frayed Rear (7.1.2 (b) (ii))**MOT #7** 2019-09-06 10:20**MOT test number** 603305661653**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Seat belt webbing slightly damaged or frayed Rear (7.1.2 (b) (ii))**Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**MOT #6** 2018-09-03 10:52**MOT test number** 846119627578**Result** ✓ Passed**MOT #5** 2018-09-03 09:23**MOT test number** 573455984073**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**MOT #4** 2017-09-18 15:37**MOT test number** 634951764795**Result** ✓ Passed**MOT #3** 2016-09-12 09:07**MOT test number** 786878587253**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin n/s and o/s (3.5.1g)**Advice** Nearside Rear Nail in tyre aged and cracked**Advice** Rear Brake pad(s) wearing thin o/s and n/s (3.5.1g)**Advice** Offside Rear tyre aged and cracked**MOT #2** 2015-09-19 11:18**MOT test number** 870653927447**Result** ✓ Passed**MOT #1** 2014-06-03 12:07**MOT test number** 739954654107**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
4 July 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	4 July 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>BP11CEY</b>
Plate since	2024-03-28
Current registration	<b>BP11CEY</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-08-16
Last registration	2023-06-17
Complete history	<a href="#">See info</a>



Registration #1	2011-08-16	12 mi
Registration #2	2014-06-03	32.777 mi
Registration #3	2015-09-19	35.031 mi
Registration #4	2016-09-12	42.712 mi
Registration #5	2017-09-18	52.754 mi
Registration #6	2018-09-03	60.792 mi
Registration #7	2018-09-03	60.792 mi
Registration #8	2019-09-06	70.223 mi
Registration #9	2019-09-06	70.223 mi
Registration #10	2019-09-06	70.223 mi
Registration #11	2019-09-06	70.223 mi
Registration #12	2019-09-06	70.223 mi
Registration #13	2019-09-06	70.223 mi
Registration #14	2019-09-06	70.223 mi
Registration #15	2019-09-06	70.223 mi
Registration #16	2019-09-06	70.223 mi
Registration #17	2019-09-06	70.223 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	76%
Pedestrian	42%
Safety systems	99%
Overall rating	79%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1845 mm
Height	1672 mm
Length	4573 mm
Wheel base	2770 mm
Kerb weight	1430 kg
Max. allowed weight	2128 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	D172973
---------------	---------