



report date: 2024-03-29

General information

Make	SUZUKI
Model	WAGON-R+ JLX S/T
Colour	Green
Year of manufacture	2005
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-05-26
Pictures	8
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-05-09
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #17	2023-04-26 11:01
MOT test number	258021252407
Result	✓ Passed
Next expiry date	2024-05-09
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16	2023-04-25 10:00
MOT test number	367393760943
Result	✗ Failed
Fail	Stop lamp(s) all not working (4.3.1 (a) (iii))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2022-05-10 11:20
MOT test number	262232333271
Result	✓ Passed

**MOT #14** 2021-03-31 12:32**MOT test number** 643525868708**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2019-11-20 09:59**MOT test number** 877583014272**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin 4mm (1.1.13 (a) (ii))**MOT #12** 2018-11-13 11:39**MOT test number** 368192532715**Result** ✓ Passed**MOT #11** 2017-11-07 10:20**MOT test number** 993183142536**Result** ✓ Passed**MOT #10** 2016-11-09 10:46**MOT test number** 909269277119**Result** ✓ Passed**MOT #9** 2015-11-10 13:36**MOT test number** 725382726248**Result** ✓ Passed**MOT #8** 2014-11-05 09:18**MOT test number** 575849004332**Result** ✓ Passed



MOT #7	2013-11-11 10:04
---------------	------------------

MOT test number	835345813369
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-11-23 14:13
---------------	------------------

MOT test number	666398522348
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2011-12-01 10:10
---------------	------------------

MOT test number	947135231366
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2011-02-28 16:46
---------------	------------------

MOT test number	176419851006
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-03-02 09:13
---------------	------------------

MOT test number	363021260043
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2009-02-17 15:40
---------------	------------------

MOT test number	301148849093
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2008-03-03 11:37
---------------	------------------

MOT test number	640623368028
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
---------------	---



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
9 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	FX05XNG
Plate since	2019-09-29
Current registration	FX05XNG
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-03-01
Last registration	2023-04-26
Complete history	See info



Registration #1	2005-03-01	29 mi
Registration #2	2008-03-03	12.641 mi
Registration #3	2009-02-17	12.981 mi
Registration #4	2010-03-02	13.302 mi
Registration #5	2011-02-28	13.674 mi
Registration #6	2011-12-01	14.015 mi
Registration #7	2012-11-23	14.513 mi
Registration #8	2013-11-11	14.902 mi
Registration #9	2014-11-05	15.243 mi
Registration #10	2015-11-10	15.711 mi
Registration #11	2016-05-20	16.179 mi
Registration #12	2017-05-20	16.647 mi
Registration #13	2018-05-20	17.115 mi
Registration #14	2019-05-20	17.583 mi
Registration #15	2020-05-20	18.051 mi
Registration #16	2021-05-20	18.519 mi
Registration #17	2022-05-20	18.987 mi
Registration #18	2023-05-20	19.455 mi
Registration #19	2024-05-20	19.923 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1655 mm
Length	3645 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-1505667