





report date: 2024-03-28

General information

Make	PEUGEOT
Model	5008 E-HDI ALLURE
Colour	Black
Year of manufacture	2012
Top speed	114 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	55.4 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-14

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-01-25
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	27
Total items failed	18

MOT #15	2024-01-26 12:33
MOT test number	489988741785
Result	✓ Passed
Next expiry date	2025-01-25
Advice Rear exhaust heats shield poor-rattling	g
Advice Both front lower arm bush slightly wor	n

MOT #14	2024-01-18 11:47
MOT test number	463558548598
Result	X Failed
Advice Rear exhaust heats shield poor-rattling	
Fail Front Windscreen washer not working cannot hear pump (3.5 (a))	
Advice Both front lower arm bush slightly worn	

MOT #13	2	022-12-30 11:49
MOT test	number	420047593620
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #12 2022-01-21 07:47

MOT test number 915446350641

MOT #11 2020-10-07 11:16

MOT test number 404000911922

Result

Passed

MOT #10 2020-10-06 10:34

MOT test number 258373170868

Result X Failed

Fail Offside Headlamp light source and lamp not compatible wrong patern (4.1.4 (c))

Fail Nearside Front Inner Road wheel badly distorted (5.2.2 (c) (i))

MOT #9 2019-09-23 12:26

MOT test number 279500289372

Result \rightarrow Passed

Advice Front Registration plate insecure but not likely to fall off cracked (0.1 (a))

MOT #8 2019-09-21 09:04

MOT test number 502523976733

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Registration plate insecure but not likely to fall off cracked (0.1 (a))

CarCheck.co.uk page 4/14



MOT #7

YH62WXY report date: 2024-03-28

2018-09-25 14:31

MOT test number 579589913763

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2017-10-03 11:48

MOT test number 879715602276

Result \rightarrow Passed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Rear tyre sidewall damage

Advice Offside Rear tyre sidewall damage

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #5 2017-10-02 10:02

MOT test number 108577056472

Result X Failed

Advice Nearside Front tyre sidewall damage

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Rear tyre sidewall damage

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front tyre worn on inside

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Offside Front tyre sidewall damage

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Offside Rear tyre sidewall damage

Fail Nearside Registration plate lamp not working (1.1.C.1d)

Advice Nearside Front tyre worn on inside

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #4 2016-10-05 09:48

MOT test number 339380638201

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/14



report date: 2024-03-28

2016-10-01 09:51 **MOT** #3 761616684540 **MOT** test number Result × Failed Fail Nearside Stop lamp not working (1.2.1b) Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b) **Advice** Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Stop lamp not working (1.2.1b) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #2

MOT test number

923603795510

Result

Advice Nearside Rear child seat fitted

2015-10-16 11:45

y Passed

MOT test number
946911661294

Result
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Rear child seat fitted

Fail Offside Headlamp aim too low (1.8)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner	historv
OWNER	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

e which misterly	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	MK ME
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combont info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-10-19
Last registration	2024-01-26
Complete history	See info



Registration #1	2012-10-19	9 mi
Registration #2	2015-10-16	28.480 mi
Registration #3	2015-10-16	28.480 mi
Registration #4	2016-10-01	35.229 mi
Registration #5	2016-10-05	35.250 mi
Registration #6	2017-10-02	41.614 mi
Registration #7	2017-10-03	41.614 mi
Registration #8	2018-09-25	54.371 mi
Devictor #0	2010 00 21	66.799 mi
Registration #9	2019-09-21	00.799 1111
Registration #10	2019-09-21	00.799 1111
	2019-09-21	00.799 1111
Registration #10	2019-09-21	00.799 1111
Registration #10 Registration #11	2019-09-21	00.799 1111
Registration #10 Registration #11 Registration #12	2019-09-21	00.799 1111
Registration #10 Registration #11 Registration #12 Registration #13	2019-09-21	00.799 1111
Registration #10 Registration #11 Registration #12 Registration #13 Registration #14	2019-09-21	00.799 1111

More info >

CarCheck.co.uk page 13/14



Car features

S0225		Air conditioning

The PEUGEOT factory car options list is only available in the premium report.

S0295

S0482 S0501

S0566

S0567 S0569

View the complete PEUGEOT factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1688 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/

Number of axles 2

Engine number JBEG3090347