



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE TDI 100BHP
Colour	Yellow
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-10-07
Pictures	21
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-12
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	27
Total items failed	4

MOT #15	2023-10-13 13:30
---------	------------------

MOT test number	711347687547
-----------------	--------------

Result	✓ Passed
Next expiry date	2024-10-12
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Rear reurn spring on caliper
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement deteriorating (5.3.4 (a) (i))
Advice	Offside Rear return spring on caliper missing
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement deteriorating (5.3.4 (a) (i))

**MOT #14**

2023-10-04 08:56

MOT test number

640661474617

Result**✗ Failed**

Advice Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Brake servo defective or ineffective (1.1.10 (a) (i))

Advice Nearside Rear return spring on caliper missing

Advice Central Front Oil leak, but not excessive turbo return (8.4.1 (a) (i))

Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Advice Offside Rear return spring on caliper missing

MOT #13

2022-10-04 11:52

MOT test number

372724599972

Result**✓ Passed**

Advice Nearside Front Tyre slightly damaged/cracking or perishing also getting low - 3mm (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2022-09-29 14:50

MOT test number

586768465490

Result**✗ Failed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Minor Offside Front Tyre obviously under inflated (5.2.3 (l))

Advice Nearside Front Tyre slightly damaged/cracking or perishing also getting low - 3mm (5.2.3 (d) (ii))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Minor Nearside Front Tyre obviously under inflated (5.2.3 (l))

**MOT #11** 2021-09-24 11:18**MOT test number** 580319977874**Result** ✓ Passed**Advice** Engine bay and under body covers fitted obscuring testable items from view**MOT #10** 2020-12-23 12:20**MOT test number** 275133729777**Result** ✓ Passed**MOT #9** 2020-01-09 15:07**MOT test number** 437568742248**Result** ✓ Passed**MOT #8** 2019-01-10 14:08**MOT test number** 372980487240**Result** ✓ Passed**Advice** N/s/r and o/s/r tyres perishing/cracking**MOT #7** 2017-12-15 15:08**MOT test number** 977686486335**Result** ✓ Passed**MOT #6** 2016-12-13 13:55**MOT test number** 155649994383**Result** ✓ Passed**MOT #5** 2015-12-16 11:15**MOT test number** 347192382010**Result** ✓ Passed

**MOT #4** 2014-12-10 11:51**MOT test number** 358624144371**Result** ✓ Passed**Notice** Front tyres wearing slightly on inside edges**MOT #3** 2013-12-12 12:21**MOT test number** 805106143381**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-01-07 13:09**MOT test number** 887627603078**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2011-12-13 11:28**MOT test number** 406007541368**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
12 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VK58XZE
Plate since	2019-06-29
Current registration	 VK58XZE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-01-09
Last registration	2023-10-13
Complete history	See info



Registration #1	2009-01-09	17 mi
Registration #2	2011-12-13	5.496 mi
Registration #3	2013-01-07	7.162 mi
Registration #4	2013-12-12	8.912 mi
Registration #5	2014-12-10	10.591 mi
Registration #6	2015-12-16	12.070 mi
Registration #7	2016-12-13	13.669 mi
Registration #8	2017-12-15	15.059 mi
Registration #9	2019-01-10	19.848 mi
Registration #10	2019-01-10	20.277 mi
Registration #11	2019-01-10	20.277 mi
Registration #12	2019-01-10	20.277 mi
Registration #13	2019-01-10	20.277 mi
Registration #14	2019-01-10	20.277 mi
Registration #15	2019-01-10	20.277 mi
Registration #16	2019-01-10	20.277 mi
Registration #17	2019-01-10	20.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1370 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BSW 020646