



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D S
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-26
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #12	2022-08-12 07:14
MOT test number	533937979171
Result	✓ Passed
Next expiry date	2023-08-11
Advice	Rear Tyre slightly damaged/cracking or perishing Nearside/Offside (5.2.3 (d) (ii))

MOT #11	2021-07-26 09:01
MOT test number	536993592878
Result	✓ Passed

MOT #10	2020-12-18 10:08
MOT test number	550582689945
Result	✓ Passed
Advice	Engine cover fitted and under tray fitted

MOT #9	2019-12-19 10:55
MOT test number	778805013533
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively lipped slightly (1.1.14 (a) (i))
Advice	Engine cover and Under-Tray cover fitted
Advice	Front Brake disc worn, but not excessively lipped slightly (1.1.14 (a) (i))

MOT #8	2018-12-20 11:19
MOT test number	440999450530
Result	✓ Passed
Advice	Engine cover and Under-Tray cover fitted
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #7** 2017-12-19 12:24**MOT test number** 507136689278**Result** ✓ Passed**MOT #6** 2017-01-05 13:57**MOT test number** 665108313030**Result** ✓ Passed**Advice** Offside Front tyre wearing on inner edge**MOT #5** 2016-01-12 12:46**MOT test number** 369400907178**Result** ✓ Passed**MOT #4** 2015-01-20 14:00**MOT test number** 158100725065**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Small stonechips in windscreen**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-02-05 15:36**MOT test number** 196626334037**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-02-05 15:36
MOT test number	737426234099
Result	✗ Failed
Pass with rectification	Offside Main beam 'tell-tale' not working (1.7.4c)
Notice	Under-trays fitted obscuring some underside components

MOT #1	2013-02-21 16:36
MOT test number	676902653017
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Front wiper blades poor could be improved



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-03-24
Last registration	2022-08-12
Complete history	See info



Registration #1	2010-03-24	27 mi
Registration #2	2013-02-21	19.625 mi
Registration #3	2014-02-05	24.606 mi
Registration #4	2015-01-20	29.236 mi
Registration #5	2016-01-12	35.425 mi
Registration #6	2017-01-05	39.838 mi
Registration #7	2017-12-19	44.092 mi
Registration #8	2018-05-29	50.277 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2020-05-29	60.277 mi
Registration #11	2021-05-29	65.277 mi
Registration #12	2022-05-29	70.277 mi
Registration #13	2022-08-12	71.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	727050
---------------	--------