





report date: 2024-03-29

General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Grey
Year of manufacture	2007
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



Internet history

entry 1	E	n	tr	ъ	1
---------	---	---	----	---	---

Lifety 1	
Date	2022-01-22
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-06-11
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #16	2023-06-12 13:50
MOT test number	662023843475
Result	✓ Passed
Next expiry date	2024-06-11
Advice Front Upper Shock absorbers has a slightly worn bush Both front up mountings bush / bearing (5.3.2 (c))	pper shock absorber top

MOT #15		2022-05-13 11:48
MOT test	number	255843888780
Result		✓ Passed
Advice	Offside Child Seat fitted not allowing full inspection of adult belt central	
Advice	Offside Play in steering rack inner joint(s)	

MOT #14		2021-05-14 13:53
MOT test	number	530147882886
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Engine covers and undertrays fitted covering some components	

CarCheck.co.uk page 3/13



MOT #13 2021-05-13 09:38

MOT test number 260948232059

Result X Failed

Fail Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Nearside Rear Suspension arm pin or bush likely to become detached trailing arm bush (5.3.4 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Engine covers and undertrays fitted covering some components

MOT #12 2020-05-15 09:31

MOT test number 177925665367

Result ✓ Passed

MOT #11 2019-05-08 09:33

MOT test number 834500253178

Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm,inner edge worn (5.2.3 (e))

MOT #10 2018-05-15 10:25

MOT test number 736408764597

Result \(\sqrt{Passed}\)

CarCheck.co.uk page 4/13



MOT #9 2017-05-02 08:58 MOT test number 672037796340

MOT #8 2016-05-18 10:54

MOT test number 788441271507

Result ✓ Passed

Advice Offside Front tyre wearing on edges

MOT #7 2015-06-29 08:58

MOT test number 867390985111

Notice O\S\R tyre wearing on inside edge

MOT #6 2014-06-24 12:30

MOT test number 989665674176

Result

Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5 2013-06-27 16:43

MOT test number 527208573151

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #4 2012-06-27 13:55

MOT test number 646609472154

Result ✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)

CarCheck.co.uk page 5/13



MOT #3 2011-06-23 15:21 **MOT test number** 177244971149 ✓ Passed Result MOT #2 2011-06-23 09:26 515344571146 **MOT test number** × Failed Result Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-06-18 12:59
MOT test number	503679360148
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	11 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK ON THE PROPERTY OF THE PROP
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-06-27
Last registration	2023-06-12
Complete history	See info



Registration #1	2007-06-27	17 mi
Registration #2	2010-06-18	35.590 mi
Registration #3	2011-06-23	47.252 mi
Registration #4	2011-06-23	47.252 mi
Registration #5	2012-06-27	58.601 mi
Registration #6	2013-06-27	68.629 mi
Registration #7	2014-06-24	77.056 mi
Registration #8	2015-06-29	85.085 mi
Registration #9	2016-05-18	92.067 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13