




report date: 2024-03-28

General information

Make	NISSAN
Model	PRIMASTAR DCI SE SHR P/V
Colour	White
Year of manufacture	2013
Top speed	160 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	290 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	41.5 mpg
Consumption combined	38.2 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-07-15
Pictures	21
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-05-26
<b>MOT pass rate</b>	57 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	6
<b>Total advice items</b>	26
<b>Total items failed</b>	5

**MOT #14** 2023-05-24 15:05**MOT test number** 554829985700**Result** Passed**Next expiry date** 2024-05-26

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))

**MOT #13** 2023-05-24 08:59**MOT test number** 324993723909**Result** Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))

**MOT #12** 2022-05-27 14:49**MOT test number** 284075982496**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #11** 2021-03-31 15:35**MOT test number** 370142781360**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MOT #10** 2021-03-23 14:56**MOT test number** 718283676033**Result** ✗ Failed**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2020-01-10 10:31**MOT test number** 946645187659**Result** ✓ Passed

**MOT #8** 2020-01-09 09:12**MOT test number** 285051306288**Result** ✗ Failed**MAJOR** Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Suspension arm ball joint excessively worn Bottom ball joint (5.3.4 (a) (i))**MAJOR** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2018-12-31 11:58**MOT test number** 741563841535**Result** ✓ Passed**MOT #6** 2018-12-29 12:59**MOT test number** 480749490603**Result** ✗ Failed**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #5** 2017-12-27 14:04**MOT test number** 969367223087**Result** ✓ Passed**MOT #4** 2016-12-28 14:17**MOT test number** 743836305571**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #3** 2016-12-20 15:50**MOT test number** 549684009889**Result** ✗ Failed**Fail** Offside Front Brake pipe excessively corroded to rear marked yellow (3.6.B.2c)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**MOT #2** 2015-12-18 17:24**MOT test number** 806327833367**Result** ✓ Passed**MOT #1** 2015-12-16 12:33**MOT test number** 256994250455**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake application uneven (3.7.B.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear brake application uneven (3.7.B.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
26 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	26 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>YY62PJV</b>
Plate since	2019-03-28
Current registration	<b>YY62PJV</b>
Plate since	2019-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-01-08
Last registration	2023-05-24
Complete history	<a href="#">See info</a>



Registration #1	2013-01-08	21 mi
Registration #2	2015-12-16	43.092 mi
Registration #3	2015-12-18	43.113 mi
Registration #4	2016-12-20	62.607 mi
Registration #5	2016-12-28	62.674 mi
Registration #6	2017-12-27	82.065 mi
Registration #7	2018-12-29	89.540 mi
Registration #8	2018-12-31	89.544 mi
Registration #9	2019-05-29	95.377 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	114800