




report date: 2024-03-28

General information

Make	CITROEN
Model	C4 PICASSO GRAND E-HDI AIRDREAM EXCLUSIVE PLUS ETG6
Colour	Silver
Year of manufacture	2014
Top speed	117 mph
0 - 60 mph	12.6 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B





Internet history

Entry 4

Date	2023-03-09
Pictures	10
Listing price	View report



source: cargurus.co.uk

Entry 3

Date	2023-03-09
Pictures	10
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2021-12-03
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-02
------	------------

Pictures

39

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2025-03-11
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	20
Total items failed	10

MOT #10 2024-03-12 12:33**MOT test number** 644659606556**Result** Passed**Next expiry date** 2025-03-11

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing worn on edge (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing worn on edge (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #9 2023-03-10 16:05**MOT test number** 510227965898**Result** Passed**MOT #8** 2022-02-02 16:50**MOT test number** 296914963872**Result** Passed

**MOT #7** 2022-01-12 16:05**MOT test number** 260257862561**Result** ✗ Failed**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**MOT #6** 2020-07-24 14:11**MOT test number** 628006493318**Result** ✓ Passed**MOT #5** 2019-07-25 13:23**MOT test number** 977411941388**Result** ✓ Passed**Advice** Amber tyre pressure monitoring system warning lamp indicating fault**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Engine bay covers obscuring some components**Advice** Rear Brake pad(s) wearing thin close too wear indicators (1.1.13 (a) (ii))**Advice** Nearside Rear Passenger door panel damaged**Advice** Under trays obscuring power steering components & rear suspension components & mountings

**MOT #4** 2019-07-22 14:04**MOT test number** 258043009403**Result** ✗ Failed

- Advice** Amber tyre pressure monitoring system warning lamp indicating fault
- Advice** Engine bay covers obscuring some components
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Nearside Rear Passenger door panel damaged
- Advice** Rear Brake pad(s) wearing thin close too wear indicators (1.1.13 (a) (ii))
- Advice** Under trays obscuring power steering components & rear suspension components & mountings
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #3 2018-07-27 11:38**MOT test number** 169440426134**Result** ✓ Passed**MOT #2** 2018-07-27 11:38**MOT test number** 804994095482**Result** ✗ Failed

- Pass with rectification** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Pass with rectification** Tyre pressure monitoring system inoperative (5.2.3 (h) (ii))
- Pass with rectification** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Pass with rectification** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Pass with rectification** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Pass with rectification** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))



MOT #1	2017-09-07 12:00
MOT test number	865446889558
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	11 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-30
Last registration	2024-03-12
Complete history	See info



Registration #1	2014-09-30	7 mi
Registration #2	2017-09-07	32.772 mi
Registration #3	2018-07-27	40.039 mi
Registration #4	2018-07-27	40.039 mi
Registration #5	2019-07-22	55.174 mi
Registration #6	2019-07-25	55.189 mi
Registration #7	2020-07-24	69.550 mi
Registration #8	2020-09-29	75.277 mi
Registration #9	2020-09-29	75.277 mi
Registration #10	2020-09-29	75.277 mi
Registration #11	2020-09-29	75.277 mi
Registration #12	2020-09-29	75.277 mi
Registration #13	2020-09-29	75.277 mi
Registration #14	2020-09-29	75.277 mi
Registration #15	2020-09-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1656 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1320 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBEX3019183