



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Red
Year of manufacture	2008
Top speed	129 mph
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-24
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	20
Total items failed	14

MOT #18	2023-10-09 08:24
MOT test number	269421031217
Result	✓ Passed
Next expiry date	2024-10-08
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Side repeater slightly discoloured (4.4.3 (a))
Advice	Nearside Front Side repeater slightly discoloured (4.4.3 (a))

MOT #17	2023-10-09 08:24
MOT test number	315723865110
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Side repeater slightly discoloured (4.4.3 (a))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Side repeater slightly discoloured (4.4.3 (a))

**MOT #16**

2022-09-22 15:14

MOT test number

696182829825

Result

✓ Passed

- Advice** Front Lower Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29% (1.2.1 (b) (i))
- Advice** Side repeater slightly discoloured both sides (4.4.3 (a))

MOT #15

2022-09-02 10:40

MOT test number

228233415101

Result

✗ Failed

- Fail** Rear Brakes imbalanced across an axle 44% (1.2.1 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Oil filter corroded
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Corroded at rear
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))



MOT #14	2021-09-16 15:05
----------------	------------------

MOT test number	365519681523
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2021-09-07 16:51
----------------	------------------

MOT test number	313999682121
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
-------------	---

MOT #12	2021-03-15 15:10
----------------	------------------

MOT test number	468257013288
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2019-12-16 13:41
----------------	------------------

MOT test number	944761589070
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2019-02-01 12:46
----------------	------------------

MOT test number	432276543509
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #9** 2019-02-01 10:21**MOT test number** 181082582168**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Side repeater incorrect colour (4.4.3 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2017-12-27 13:28**MOT test number** 462982445666**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-01-20 14:02**MOT test number** 674898661595**Result** ✓ Passed**MOT #6** 2016-02-01 14:02**MOT test number** 128237224546**Result** ✓ Passed**MOT #5** 2015-01-26 09:11**MOT test number** 427766725004**Result** ✓ Passed

**MOT #4** 2014-01-29 11:08**MOT test number** 147139924415**Result** ✓ Passed**MOT #3** 2013-01-31 16:27**MOT test number** 427081133076**Result** ✓ Passed**MOT #2** 2013-01-31 09:32**MOT test number** 445211033034**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2011-08-09 11:14**MOT test number** 369211521273**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
8 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RA08NJY
Plate since	2019-03-28
Current registration	RA08NJY
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-08-19
Last registration	2023-10-09
Complete history	See info



Registration #1	2008-08-19	12 mi
Registration #2	2011-08-09	14.980 mi
Registration #3	2013-01-31	23.448 mi
Registration #4	2013-01-31	23.448 mi
Registration #5	2014-01-29	26.691 mi
Registration #6	2015-01-26	29.030 mi
Registration #7	2016-02-01	32.987 mi
Registration #8	2017-01-20	37.679 mi
Registration #9	2017-12-27	40.162 mi
Registration #10	2019-02-01	46.635 mi
Registration #11	2019-05-29	51.377 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi
Registration #19	2019-05-29	51.377 mi
Registration #20	2019-05-29	51.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC8188549