



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES
Model	VIANO CDI LONG AMBIENTE
Colour	Silver
Year of manufacture	2009
Top speed	108 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.1 mpg
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-06
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	21
Total items failed	6

MOT #13	2023-08-10 15:15
MOT test number	820192504687
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Brake pipe corroded, covered in grease or other material covered in protective grease (1.1.11 (c))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #12	2023-08-03 14:02
MOT test number	236833545964
Result	✗ Failed
Fail	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Brake pedal wearing smooth (1.1.2 (c))
Fail	Rear Exhaust silencer insecure (8.1.1 (b) (i))
Fail	Emissions unable to be completed back box snapped (8.2.2.2 (e))
Advice	Brake pipe corroded, covered in grease or other material covered in protective grease (1.1.11 (c))

**MOT #11** 2021-07-12 11:27**MOT test number** 754826277057**Result** ✓ Passed**MOT #10** 2021-07-09 11:07**MOT test number** 427673704486**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 215/65/16 (5.2.3 (d) (i))**Advice** Offside Rear screw in tread**MOT #9** 2020-07-02 08:35**MOT test number** 661842487305**Result** ✓ Passed**Advice** Rear rear diff oil seal leaking**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-05-31 09:12**MOT test number** 499139565632**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Oil leak, but not excessive from rear diff (8.4.1 (a) (i))**MOT #7** 2018-05-09 11:07**MOT test number** 927248123220**Result** ✓ Passed

**MOT #6** 2017-05-08 10:09**MOT test number** 753833788848**Result** ✓ Passed**Advice** Rear Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-05-09 17:03**MOT test number** 565473130547**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured both nearside & offside (1.4.A.2f)**Advice** Rear Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2015-03-18 13:19**MOT test number** 129577075438**Result** ✓ Passed**MOT #3** 2013-10-15 16:52**MOT test number** 308708383431**Result** ✓ Passed



MOT #2	2013-05-18 11:27
MOT test number	917408833146
Result	✓ Passed
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Under-trays fitted obscuring some underside components
Advice	Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2012-06-06 13:28
MOT test number	605448252145
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
15 April 2024

✓

MOT

Expires:  
9 August 2024

Tax status	Expired at 15 April 2024
Days left	14 days too late
MOT expiry date	9 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>XXXXX</b>
Plate since	2024-03-28
Current registration	 <b>XXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-06-04
Last registration	2023-08-10
Complete history	<a href="#">See info</a>



Registration #1	2009-06-04	19 mi
Registration #2	2012-06-06	27.619 mi
Registration #3	2013-05-18	31.713 mi
Registration #4	2013-10-15	33.177 mi
Registration #5	2015-03-18	51.044 mi
Registration #6	2016-05-09	56.039 mi
Registration #7	2017-05-08	64.547 mi
Registration #8	2018-05-09	69.688 mi
Registration #9	2019-05-09	75.729 mi
Registration #10	2020-05-09	81.770 mi
Registration #11	2021-05-09	87.811 mi
Registration #12	2022-05-09	93.852 mi
Registration #13	2023-05-09	99.893 mi
Registration #14	2024-05-09	105.934 mi
Registration #15	2025-05-09	111.975 mi

More info >



Safety ratings

NCAP rating

★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1906 mm
Height	1875 mm
Length	4993 mm
Wheel base	3200 mm
Kerb weight	2090 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	64698051753109