





report date: 2024-03-28

General information

Make	TOYOTA
Model	LANDCRUISER D-4D LC4 8 SEAT
Colour	Black
Year of manufacture	2004
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	164 BHP
Max. torque	410 Nm at 2.000 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	243 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-28


Internet history

Entry 1

Date 2022-04-20

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-06-08
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	8
Total items failed	11

MOT #20	2023-06-09 15:50
MOT test number	182518158139
Result	✓ Passed
Next expiry date	2024-06-08
Advice Front Anti-roll bar linkage ball joint has slight play Both. (5.3.4 (a) (i))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #19	2023-06-01 14:45
MOT test number	472502064787
Result	X Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure ingress of dirt (6.1.7 (g) (ii))	e, no longer prevents the
Advice Front Anti-roll bar linkage ball joint has slight play Both. (5.3.4 (a) (i))	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecuingress of dirt (6.1.7 (g) (ii))	re, no longer prevents the
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #18	2022-05-30 11:50
MOT test number	549330261621
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

 MOT #17
 2020-10-22 08:51

 MOT test number
 265317060819

 Result
 ✓ Passed

Advice Front Items removed from driver's view prior to test

MOT #16 2019-10-25 10:04

MOT test number 925507698353

Result \sqrt{Passed}

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #15 2018-10-18 14:21

MOT test number 880880126731

Result Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #14 2018-10-18 14:21

MOT test number 432063900133

Result X Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a))

MOT #13 2017-10-25 17:31

MOT test number 990794178343

Result \rightarrow Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #	12	2017-10-24 09:47
MOT te	st number	493534219637
Result		≍ Failed
Fail	Rear fog lamp not working (1.3.2b)	
Fail	Supplementary Restraint System warning lamp indicates a fault (5.4.2)	
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Battery insecure (1.9.1)	

MOT #11		2016-10-27 13:52
MOT test number		611790754570
Result		✓ Passed
MOT #10		2015-10-26 15:56
MOT test number		757675983281
Result		✓ Passed
MOT #9		2014-10-22 18:05
MOT test number		536665894264
Result		✓ Passed
MOT #8		2014-10-22 18:05
MOT test number		297395294213
Result		X Failed
Pass with rectification	Front Headlamp not working on dipped beam (1.7.5a)	

MOT #7	2013-10-23 17:34
MOT test number	175866593299
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6	2012-10-29 13:58
MOT test number	696873102305
Result	✓ Passed
MOT #5	2011-10-27 17:59
MOT test number	226230901388
Result	✓ Passed
MOT #4	2010-10-29 19:57
MOT test number	533272700317
Result	✓ Passed
MOT #3	2009-11-02 12:15
MOT test number	910616009349
Result	✓ Passed
MOT #2	2008-12-01 11:40
MOT test number	813426838364
Result	✓ Passed
MOT #1	2007-10-30 16:25
MOT test number	440143407324
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	8 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-11-25
Last registration	2023-06-09
Complete history	See info



Registration #1	2004-11-25	7 mi
Registration #2	2007-10-30	50.150 mi
Registration #3	2008-12-01	52.535 mi
Registration #4	2009-11-02	54.854 mi
Registration #5	2010-10-29	56.524 mi
Registration #6	2011-10-27	62.215 mi
Registration #7	2012-10-29	66.433 mi
Registration #8	2013-10-23	70.990 mi
Registration #9	2014-10-22	74.544 mi
Registration #10	2015-10-26	78.449 mi
Registration #11	2016-10-27	80.756 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		77.777 46
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.727 es
Registration #20		11.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

- C		_		
II)In	nensioi	ns ん '	weiahi	r

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	2000 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	1KD1199320

CarCheck.co.uk page 13/13