



**R057VLK**

report date: 2024-03-28

General information

Make	AUDI
Model	A3 16V SPECIAL EDITION
Colour	Blue
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	169 g/km
CO2 label	H





MOT history

MOT expiry date	2025-02-21
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	47
Total items failed	22

MOT #21	2024-02-20 18:16
---------	------------------

MOT test number	604590550565
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-21
------------------	------------

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Coolant leak
- Advice** Bonnet primary retaining device slightly deteriorated (3.1 (c))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Rear Direction indicator slightly discoloured both sides (4.4.3 (a))

**MOT #20**

2023-02-20 14:46

**MOT test number**

915796643253

**Result**

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush both sides (5.3.4 (a) (i))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Shock absorbers has light misting of oil both sides (5.3.2 (b))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-02-16 15:00

**MOT test number**

506213381438

**Result**

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

**MOT #18**

2022-02-11 14:14

**MOT test number**

584673395501

**Result**

✗ Failed

**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Rear bush (5.3.4 (a) (i))**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt  
(5.3.4 (b) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))**Fail** Emissions not tested Due to excessive smoke (8.2.1.2 (d))**MOT #17**

2021-02-22 21:03

**MOT test number**

519903574670

**Result**

✓ Passed

**MOT #16**

2021-02-22 20:48

**MOT test number**

197073645231

**Result**

✗ Failed

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #15**

2021-02-04 16:55

**MOT test number**

563478158337

**Result**

✗ Failed

**Fail** Offside Headlamp aim too high (4.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Emissions not tested all readings exceeding limits,intermittant misfire (8.2.1.2 (d))**Fail** Nearside Brake cable has restricted free movement (1.1.15 (e))

**MOT #14**

2021-01-06 13:17

**MOT test number**

223077074615

**Result**

✗ Failed

- Fail** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp aim too low (4.1.2 (a))

**MOT #13**

2019-07-26 11:38

**MOT test number**

234014308719

**Result**

✓ Passed

- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin approx 2-3mm left outer pads cannot see inner pads to comment on condition (1.1.13 (a) (ii))
- Advice** Coolant empty
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bad inner and outer tread wear (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Nail in tyre

**MOT #12** 2018-07-24 11:43**MOT test number** 187199870387**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Advise rear suspension coil spring possibly broken lower.**MOT #11** 2018-07-24 09:26**MOT test number** 542496880703**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Advise rear suspension coil spring possibly broken lower.**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #10** 2017-07-06 13:39**MOT test number** 243698952068**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2016-07-23 11:45**MOT test number** 364145082780**Result** ✓ Passed

**MOT #8** 2015-07-16 11:54**MOT test number** 985267595163**Result** ✓ Passed

- Notice** Engine management light is on
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

**MOT #7** 2014-07-25 13:22**MOT test number** 426296904208**Result** ✓ Passed**MOT #6** 2013-09-02 09:43**MOT test number** 616895243228**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside front tyre side wall damaged
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #5** 2012-08-29 15:35**MOT test number** 517252642219**Result** ✓ Passed**MOT #4** 2012-08-29 09:43**MOT test number** 888882342238**Result** ✗ Failed

- Fail** Offside Registration plate lamp not fitted (1.1.C.1b)



MOT #3	2011-08-24 09:01
MOT test number	305136431491
Result	✓ Passed
MOT #2	2010-09-10 09:00
MOT test number	220093250232
Result	✓ Passed
MOT #1	2010-09-10 09:00
MOT test number	853303150220
Result	✗ Failed
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
21 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	21 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-19
Last registration	2024-02-20
Complete history	<a href="#">See info</a>



Registration #1	2007-09-19	11 mi
Registration #2	2010-09-10	31.970 mi
Registration #3	2011-08-24	41.855 mi
Registration #4	2012-08-29	50.600 mi
Registration #5	2012-08-29	50.602 mi
Registration #6	2013-09-02	57.510 mi
Registration #7	2014-07-25	60.503 mi
Registration #8	2015-07-16	64.054 mi
Registration #9	2016-07-23	67.291 mi
Registration #10	2017-07-06	72.078 mi
Registration #11	2018-07-24	77.663 mi
Registration #12	2019-06-20	81.337 mi
Registration #13	2020-06-20	85.011 mi
Registration #14	2021-06-20	88.685 mi
Registration #15	2022-06-20	92.359 mi
Registration #16	2023-06-20	96.033 mi
Registration #17	2024-02-20	99.707 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4203 mm
Wheel base	2578 mm
Kerb weight	1205 kg
Max. allowed weight	1765 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	BSE 345284