



LM64NWW

report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	2014
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-06-21
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-29
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #9	2023-06-30 14:11
MOT test number	258294397409
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Rear Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
Advice	Front Tyre slightly damaged/cracking or perishing BOTH (5.2.3 (d) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Nail in tyre

MOT #8	2022-06-30 13:34
MOT test number	126373161907
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7	2021-08-17 13:15
MOT test number	919838918954
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Exhaust silencer slightly loose (8.1.1 (b) (i))

**MOT #6** 2020-08-27 14:09**MOT test number** 218404963542**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #5** 2019-08-23 15:13**MOT test number** 775453533552**Result** ✓ Passed**Advice** Rear rear exhaust box rusty**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2019-08-23 13:48**MOT test number** 685976268432**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Rear rear exhaust box rusty**MOT #3** 2018-08-24 16:25**MOT test number** 638798551451**Result** ✓ Passed**MOT #2** 2018-08-24 10:28**MOT test number** 282707495178**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))



MOT #1	2017-08-31 11:53
MOT test number	331778757541
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-31
Last registration	2023-06-30
Complete history	See info



Registration #1	2014-10-31	29 mi
Registration #2	2017-08-31	14.637 mi
Registration #3	2018-08-24	22.466 mi
Registration #4	2018-08-24	22.466 mi
Registration #5	2019-08-23	29.508 mi
Registration #6	2019-08-23	29.509 mi
Registration #7	2019-08-23	29.509 mi
Registration #8	2019-08-23	29.509 mi
Registration #9	2019-08-23	29.509 mi
Registration #10	2019-08-23	29.509 mi
Registration #11	2019-08-23	29.509 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	0798077