



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE V6
Colour	Silver
Year of manufacture	2003
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Engine capacity	2.496 cc
Cylinders	6
Fuel type	Petrol
Consumption city	20.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	29.4 mpg
CO2 emission	234 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-01
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-23
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	49
Total items failed	6

MOT #21 2021-11-22 12:17

MOT test number 534043319673

Result ✗ Failed

MAJOR Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength BODY SILL (5.3.6 (a) (i))

MAJOR Offside Rear Suspension arm pin or bush excessively worn TRAILING ARM BUSH (5.3.4 (a) (i))

MAJOR Anti-lock braking system warning lamp indicates an ABS fault light on dash (1.6 (b))

MAJOR Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Oil leak, but not excessive ENGINE AREA (8.4.1 (a) (i))

MAJOR Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength BODY SILL (5.3.6 (a) (i))

MAJOR Nearside Rear Suspension arm pin or bush excessively worn TRAILING ARM BUSH (5.3.4 (a) (i))

MAJOR Nearside Front Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MAJOR Offside Front Headlamp aim too low (4.1.2 (a))

**MOT #20**

2020-11-04 09:48

MOT test number

593846255353

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #19**

2020-11-04 09:31

MOT test number

655786133541

Result

✗ Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #18**

2019-11-14 09:44

MOT test number

861296026859

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Screenwash poor**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17**

2019-11-14 09:44

MOT test number

723149775775

Result**✗ Failed****Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Screenwash poor**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #16**

2018-11-13 14:26

MOT test number

341753841198

Result**✓ Passed****Advice** Both rear tyres low on tread**Advice** Crack in windscreen**MOT #15**

2018-11-13 14:26

MOT test number

523724292880

Result**✗ Failed****Advice** Both rear tyres low on tread**Advice** Crack in windscreen**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #14** 2017-11-14 14:36**MOT test number** 529730696010**Result** ✓ Passed**MOT #13** 2016-11-15 15:04**MOT test number** 120466177127**Result** ✓ Passed**MOT #12** 2015-11-24 14:48**MOT test number** 722439019928**Result** ✓ Passed**MOT #11** 2014-11-11 15:57**MOT test number** 565235314334**Result** ✓ Passed**Notice** Both front tyres low on tread**MOT #10** 2013-11-18 14:28**MOT test number** 539982323329**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2013-11-18 10:25**MOT test number** 126222323386**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2012-10-04 14:55**MOT test number** 659698072239**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2011-10-12 11:51**MOT test number** 939255581212**Result** ✓ Passed**Notice** Nail in offside front tyre**MOT #6** 2010-09-30 15:47**MOT test number** 284003770225**Result** ✓ Passed**Notice** Plastic covers prevent examination of outer sill panels**Notice** Nail in offside front tyre

**MOT #5** 2010-09-30 12:26**MOT test number** 434433070248**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nail in offside front tyre**Notice** Plastic covers prevent examination of outer sill panels**MOT #4** 2009-07-21 10:18**MOT test number** 764472509255**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2007-12-11 11:42**MOT test number** 484855547417**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2007-01-02 12:45**MOT test number** 180172707492**Result** ✓ Passed**MOT #1** 2006-09-12 10:37**MOT test number** 374685056231**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
10 December 2021

✕
MOT

Expired:
23 November 2021

Tax status	Expired at 10 December 2021
Days left	872 days too late
MOT expiry date	23 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	KG530KR
Plate since	2024-03-29
Current registration	KG530KR
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-09-30
Last registration	2021-11-22
Complete history	See info



Registration #1	2003-09-30	27 mi
Registration #2	2006-09-12	18.834 mi
Registration #3	2007-01-02	19.807 mi
Registration #4	2007-12-11	25.056 mi
Registration #5	2009-07-21	35.639 mi
Registration #6	2010-09-30	42.572 mi
Registration #7	2010-09-30	42.572 mi
Registration #8	2011-10-12	48.459 mi
Registration #9	2012-10-04	58.803 mi
Registration #10	2013-11-18	65.187 mi
Registration #11	2013-11-18	65.190 mi
Registration #12	2014-11-11	73.033 mi
Registration #13	2015-05-20	75.277 mi
Registration #14	2015-05-20	75.277 mi
Registration #15	2015-05-20	75.277 mi
Registration #16	2015-05-20	75.277 mi
Registration #17	2015-05-20	75.277 mi
Registration #18	2015-05-20	75.277 mi
Registration #19	2015-05-20	75.277 mi
Registration #20	2015-05-20	75.277 mi
Registration #21	2015-05-20	75.277 mi
Registration #22	2015-05-20	75.277 mi
Registration #23	2015-05-20	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1555 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	355658416XB