



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Blue
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2


Date	2023-12-13
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-10-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-12
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	24
Total items failed	2

MOT #12	2023-11-13 13:03
MOT test number	136714529471
Result	✓ Passed
Next expiry date	2024-11-12
Advice	Offside Rear tyre worn

MOT #11	2023-11-10 11:12
MOT test number	647257129540
Result	✗ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2022-11-09 13:07
MOT test number	962563448166
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2022-11-09 12:47**MOT test number** 786978050107**Result** ✗ Failed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**DANGEROUS** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm 2254517 (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2021-11-08 10:51**MOT test number** 976990885041**Result** ✓ Passed**MOT #7** 2021-02-09 11:39**MOT test number** 793732159787**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2020-02-10 09:10**MOT test number** 354312524092**Result** ✓ Passed

**MOT #5** 2019-02-07 13:54**MOT test number** 190936595537**Result** ✓ Passed**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing slight sidewall damage (5.2.3 (d) (ii))**MOT #4** 2019-02-07 11:51**MOT test number** 548319642943**Result** ✗ Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing slight sidewall damage (5.2.3 (d) (ii))**MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #3** 2018-02-12 16:14**MOT test number** 204137672877**Result** ✓ Passed**MOT #2** 2018-02-12 16:14**MOT test number** 765719146303**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp aim too high (1.8)



MOT #1	2017-02-22 09:42
MOT test number	992100535468
Result	✓ Passed
Advice	Nearside Front nail in tread
Advice	Offside Rear nail in tread
Advice	Nearside Rear nail in tread



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
12 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-06-29
Current registration	 XXXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-03-21
Last registration	2023-11-13
Complete history	See info



Registration #1	2014-03-21	26 mi
Registration #2	2017-02-22	14.341 mi
Registration #3	2018-02-12	17.702 mi
Registration #4	2018-02-12	17.702 mi
Registration #5	2019-02-07	30.706 mi
Registration #6	2019-02-07	30.706 mi
Registration #7	2020-02-10	45.139 mi
Registration #8	2020-02-10	45.139 mi
Registration #9	2020-02-10	45.139 mi
Registration #10	2020-02-10	45.139 mi
Registration #11	2020-02-10	45.139 mi
Registration #12	2020-02-10	45.139 mi
Registration #13	2020-02-10	45.139 mi
Registration #14	2020-02-10	45.139 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD