





report date: 2024-03-29

General information

| Make | CITROEN |
|---------------------|--|
| Model | DISPATCH M 1000 ENTERPRISE BLUEHDI S/S |
| Colour | Silver |
| Year of manufacture | 2019 |
| Top speed | 99 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 BHP |
|-------------------------|---------------------|
| Max. torque | 300 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 137 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-07-09

Pictures 20

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

| Date | 2021-05-26 | |
|------|------------|--|
| | | |

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-02-28 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 3 |
| Failed MOT tests | 2 |
| Total advice items | 11 |
| Total items failed | 6 |

| MOT #5 | 2024-02-22 17:11 |
|--|------------------|
| MOT test number | 289184798725 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-28 |
| Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 20 | 024-02-21 08:53 |
|-------------------------|---|-----------------|
| MOT test | number | 879326299809 |
| Result | | X Failed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1 | 4 (a) (ii)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | 1 (a) (ii)) |
| Advice | Front Exhaust has a minor leak of exhaust gases (6.1.2 (a)) | |
| Advice | Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Re | ear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 | (a) (ii)) |
| Fail W | Vindscreen washer provides insufficient washer liquid (3.5 (a)) | |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (| (a) (ii)) |
| Minor (4.7.1 (b) | Offside Rear Registration plate lamp inoperative in the case of multiple lamps or ligh (i)) | t sources |
| Fail Fr | ront Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 3/11



Advice

CN19JWL report date: 2024-03-29

MOT test number

Result

Advice (d) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2022-02-15 16:56 **MOT** test number 348740027818 Result Passed MOT #1 2022-02-15 11:42 **MOT** test number 474284610538 Result × Failed Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 December |
|------------------|------------------------|
| Days left | 217 |
| MOT expiry date | 28 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| * | | |
|--|-----------|-------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively. | | OEN |
| *************************************** | | |
| *************************************** | | |
| ************* | | |
| | | |
| | | |
| | | |
| | | |
| | More info | > |
| Plate changes See in this check if this CITROEN had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | 0.0.0 |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Combont info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2019-03-01 |
| Last registration | 2024-02-22 |
| Complete history | See info |



| Registration #1 | 2019-03-01 | 17 mi |
|-----------------|------------|-----------|
| Registration #2 | | 71.777 es |
| Registration #3 | | 0.777 es |
| Registration #4 | 2022-02-15 | 32.863 mi |
| Registration #5 | | 0.77 mi |
| Registration #6 | | 71.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 au |

More info >

CarCheck.co.uk page 10/11



| Dimensions & | weig | ht |
|--------------|------|----|
|--------------|------|----|

| Width | 1920 mm |
|---------------------|---------|
| Height | 1895 mm |
| Length | 4959 mm |
| Wheel base | 3275 mm |
| Kerb weight | 1533 kg |
| Max. allowed weight | 2660 kg |

Additional information

| Fuel tank capacity | 70 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of seats | 3 |
| Number of axles | 2 |
| Engine number | JCAP0072013 |

CarCheck.co.uk page 11/11