



report date: 2024-03-28

## General information

Make	NISSAN
Model	PRIMERA FLARE
Colour	Grey
Year of manufacture	2006
Top speed	117 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 2

Date	2021-08-13
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-04
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2021-10-25
-----------------	------------

MOT pass rate	71 %
---------------	------

MOT passed	12
------------	----

Failed MOT tests	5
------------------	---

Total advice items	61
--------------------	----

Total items failed	16
--------------------	----

MOT #17	2020-10-26 09:25
---------	------------------

MOT test number	846258392487
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-10-25
------------------	------------

Advice	Underside corroded in places
--------	------------------------------

Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge tyre devoid on edge (5.2.3 (e))
--------	---

Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
--------	--

Advice	Sump corroded
--------	---------------

Advice	Exhaust corroded in places
--------	----------------------------

MOT #16	2020-10-26 09:25
---------	------------------

MOT test number	271098615571
-----------------	--------------

Result	✗ Failed
--------	----------

Advice	Sump corroded
--------	---------------

Advice	Exhaust corroded in places
--------	----------------------------

Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
-------------------------	--

Advice	Underside corroded in places
--------	------------------------------

Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
--------	--

Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge tyre devoid on edge (5.2.3 (e))
--------	---



MOT #152019-04-24 16:14

MOT test number677996242817

Result

✓ Passed

- Advice

Offside Rear Nail in tyre
- Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2019-04-24 08:41

**MOT test number**

611525041559

**Result****✗ Failed**

- Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Nail in tyre
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #13**

2018-04-06 11:37

**MOT test number**

935848130621

**Result****✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases and system rusty (7.1.2)
- Advice** All rear suspension bush`s worn and starting to split
- Advice** Brake hose slightly deteriorated all (3.6.B.4d)

**MOT #12**

2018-03-26 11:23

**MOT test number**

932949069533

**Result****✗ Failed**

**Fail** Offside Front Suspension arm has excessive play in a track control arm inner bush rear bush (2.5.B.2b)

**Advice** Brake hose slightly deteriorated all (3.6.B.4d)

**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)

**Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement rear bush (2.4.G.2)

**Advice** Exhaust has a minor leak of exhaust gases and system rusty (7.1.2)

**Fail** Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Offside Lower Rear position lamp(s) not working (1.1.A.3b)

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** All rear suspension bush`s worn and starting to split

**MOT #11**

2017-03-27 15:18

**MOT test number**

819352859576

**Result****✓ Passed**

**Advice** Headlamp deteriorated but light output not reduced both (1.7.5a)

**Advice** Engine covers and undertrays fitted

**MOT #10**

2017-03-27 15:18

**MOT test number**

960040427503

**Result**

✗ Failed

**Advice** Headlamp deteriorated but light output not reduced both (1.7.5a)**Pass with rectification** Rear Braking system leaking both sides (3.6.A.1)**Advice** Engine covers and undertrays fitted**MOT #9**

2016-03-24 12:05

**MOT test number**

488107378011

**Result**

✓ Passed

**Advice** Exhaust corroded**Advice** Rear brake pads worn low**Advice** Rear Tyre worn close to the legal limit both (4.1.E.1)**Advice** Engine covers and undertrays fitted**Advice** Corrosion to suspension components**MOT #8**

2015-03-14 08:34

**MOT test number**

548003975094

**Result**

✓ Passed

**Notice** Exhaust corroded**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components

**MOT #7** 2014-02-28 09:16**MOT test number** 168139754459**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2013-02-15 18:29**MOT test number** 297776043041**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-02-15 09:36**MOT test number** 676426843013**Result** ✗ Failed**Advice** Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Notice** Engine management light**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)



**MOT #4** 2012-03-02 08:54**MOT test number** 348712362006**Result** ✓ Passed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Notice** Wiper blades worn

**MOT #3** 2011-02-04 10:35**MOT test number** 166915831406**Result** ✓ Passed**MOT #2** 2010-02-08 10:28**MOT test number** 961259130080**Result** ✓ Passed**MOT #1** 2009-02-28 14:11**MOT test number** 774699459020**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕  
**Untaxed**

**Tax expired:**  
30 August 2021

✕  
**MOT**

**Expired:**  
25 October 2021

<b>Tax status</b>	Expired at 30 August 2021
<b>Days left</b>	973 days too late
<b>MOT expiry date</b>	25 October 2021
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2020-10-26
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	20 mi
Registration #2	2009-02-28	38.526 mi
Registration #3	2010-02-08	47.883 mi
Registration #4	2011-02-04	51.101 mi
Registration #5	2012-03-02	61.039 mi
Registration #6	2013-02-15	70.580 mi
Registration #7	2013-02-15	70.580 mi
Registration #8	2014-02-28	89.454 mi
Registration #9	2015-03-14	102.700 mi
Registration #10	2016-03-24	113.768 mi
Registration #11	2016-03-24	113.768 mi
Registration #12	2016-03-24	113.768 mi
Registration #13	2016-03-24	113.768 mi
Registration #14	2016-03-24	113.768 mi
Registration #15	2016-03-24	113.768 mi
Registration #16	2016-03-24	113.768 mi
Registration #17	2016-03-24	113.768 mi
Registration #18	2016-03-24	113.768 mi
Registration #19	2016-03-24	113.768 mi
Registration #20	2016-03-24	113.768 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1482 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1361 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	448099