





report date: 2024-03-28

General information

Make	NISSAN
Model	LEAF ACENTA
Colour	Grey
Year of manufacture	2017
Top speed	87 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/11



PF17UPE

report date: 2024-03-28

Internet history

Entry 1

Date 2022-05-13

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-20
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	6
Total items failed	2

MOT #5		2023-06-08 11:08
MOT test	number	242082685038
Result		✓ Passed
Next expi	ry date	2024-06-20
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front bush	Offside Front Lower Suspension arm pin or bush worn but not resulting in e. (5.3.4 (a) (i))	xcessive movement

MOT #4	2022-06-21 15:16
MOT test number	262248841551
Result	✓ Passed
MOT #3	2021-07-16 09:57
MOT test number	763608155904
Result	✓ Passed

CarCheck.co.uk page 3/11



PF17UPE

report date: 2024-03-28

× Failed

 MOT #2
 2020-07-10 09:31

 MOT test number
 202676083116

 Result
 ✓ Passed

 MOT #1
 2020-07-08 08:47

 MOT test number
 716292013360

Result

Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



PF17UPE

report date: 2024-03-28

Tax & MOT check



MOT expiry date 20 June 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

PF17UPE

report date: 2024-03-28

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this NISSAN had different number plates.

More info >

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-07-31
Last registration	2023-06-08
Complete history	See info



Registration #1	2017-07-31	20 mi
Registration #2	2020-07-08	29.728 mi
Registration #3	2020-07-10	29.731 mi
Registration #4	2021-07-16	30.829 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1538 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 11/1: