





report date: 2024-03-28

General information

Make	CITROEN
Model	C4 GRAND BLUEHDI FLAIR S/S
Colour	Grey
Year of manufacture	2018
Top speed	123 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.499 сс
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	76.3 mpg
Consumption combined	2.8 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 3

Date 2022-05-28

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2021-12-11
------	------------

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-12-10

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-08-09
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #5	2023-08-10 12:39
MOT test number	635527750183
Result	✓ Passed
Next expiry date	2024-08-09

MOT #4	2023-08-04 13:39
MOT test number	643694615790
Result	🗙 Failed
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail Rear Brake pad(s) less than 1.5 mm thick Both rear (1.1.13 (a) (ii))	
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Advice Rear Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))	

MOT #3	2022-08-03 09:36
MOT test number	757318388482
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2021-09-06 10:40

MOT test number 830906184715

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread area/tyre perishing on outer sidewall (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread area (5.2.3 (d) (ii))

Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt

MOT #1 2021-09-03 15:41

MOT test number 381689824098

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread area/tyre perishing on outer sidewall (5.2.3 (d) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords tyre has cut and perishing on outer sidewall showing cords/cracking in tread area/tyre wearing low (5.2.3 (d) (i))

Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking in tread area (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

,		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ROEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK SIE	III
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



WK68LXT report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-09-29
Last registration	2023-08-10
Complete history	See info



Registration #1	2018-09-29	15 mi
Registration #2	2021-09-03	12.759 mi
Registration #3	2021-09-06	12.791 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		D.777 66
Registration #8		71.777 66
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1644 mm
Length	4602 mm
Wheel base	2840 mm
Kerb weight	1430 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Q3BB0036833

CarCheck.co.uk page 11/11