





report date: 2024-03-29

General information

Make	JAGUAR
Model	XF D PORTFOLIO AWD
Colour	Blue
Year of manufacture	2018
Top speed	136 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	430 Nm at 1.750 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	152 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2021-09-18

Pictures 3

Listing price <u>View report</u>







source: yesauto.com

Entry 1

Date	2021-09-17

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-10
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	20
Total items failed	0

MOT #5	2023-11-01 11:35
MOT test number	567988284878
Result	✓ Passed
Next expiry date	2024-11-10
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	

MOT #4		2022-11-11 13:06
MOT test	number	393303653999
Result		✓ Passed
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Vehicle body showing damage		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3		2022-11-10 14:35
MOT test	number	325384456017
Result		× Failed
Advice	Vehicle body showing damage	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
DANGER	ROUS Offside Rear Tyre has a tear, caused by separation or partial failur	e of its structure (5.2.3

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2021-08-16 11:22 **MOT** test number 391934137785 Result × Failed **Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 10 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	10 November 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGU have? Check it in the premium report and see all owner registrations. Download the full report here .	IAR

More info	>
Plate changes	
See in this check if this JAGUAR had different number plates.	

EXECUTE OF THE PROPERTY OF THE

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-14
Last registration	2023-11-01
Complete history	See info



Registration #1	2018-09-14	27 mi
Registration #2	2021-08-16	44.978 mi
Registration #3	2021-08-16	44.978 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	93%
Children	85%
Pedestrian	80%
Safety systems	72%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1457 mm
Length	4954 mm
Wheel base	2960 mm
Kerb weight	1696 kg
Max. allowed weight	1808 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	180613W0452204DTH

CarCheck.co.uk page 11/11