





report date: 2024-03-29

General information

Make	CITROEN
Model	C4 CACTUS PURETECH PLATINUM
Colour	Grey
Year of manufacture	2016
Top speed	108 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	118 Nm at 2.750 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-07-20
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #5	2023-07-21 10:47
MOT test number	282634513071
Result	✓ Passed
Next expiry date	2024-07-20

MOT #4	2023-06-28 15:08
--------	------------------

MOT test number 850709985063

Result	X Failed

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Offside Rear Sub-frame modified so the suspension is likely to fail other components (5.3.3 (c) (ii))

MAJOR Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Nearside Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Front Exhaust system insecure (6.1.2 (a))

DANGEROUS Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Offside Rear Suspension component damaged and seriously weakened ACCIDENT DAMAGE (5.3.3 (b) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3	2021-12-20 11:59
MOT test number	488684295000
Result	✓ Passed
MOT #2	2020-11-30 14:04
MOT test number	977682270820
Result	✓ Passed
MOT #1	2019-12-06 08:45
MOT test number	433449511675
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	بمرحاء المانحا
UWNEr	nistarv
OWILL	THISCOLY

,		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ROEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK SIE	III
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2016-12-23
Last registration	2023-07-21
Complete history	See info



Registration #1	2016-12-23	12 mi
Registration #2	2019-12-06	23.687 mi
Registration #3	2020-11-30	27.872 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1514 mm
Length	3944 mm
Wheel base	2451 mm
Kerb weight	975 kg
Max. allowed weight	1525 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B2150242811

CarCheck.co.uk page 11/11