



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 SPORT DCI L/C P/V
Colour	Red
Year of manufacture	2009
Top speed	96 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-04
Pictures	36
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-12
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	31
Total items failed	20

MOT #19 2023-07-13 11:02

MOT test number 503873648211

Result ✓ Passed

Next expiry date 2024-07-12

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))**Advice** Front Coil spring corroded Both (5.3.1 (b) (i))

MOT #18 2023-07-10 12:05

MOT test number 676836437927

Result ✗ Failed**Advice** Front Coil spring corroded Both (5.3.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #17**

2022-07-07 11:11

MOT test number

327752181190

Result

✓ Passed

Advice

Brake pipe corroded, covered in grease or other material Both nearside and offside rear (1.1.11 (c))

Advice

Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

MOT #16

2022-07-07 10:27

MOT test number

604977762071

Result

✗ Failed

Advice

Brake pipe corroded, covered in grease or other material Both nearside and offside rear (1.1.11 (c))

Pass with rectification

Nearside Front Headlamp aim too low (4.1.2 (a))

Fail

Offside Rear Service brake excessively binding (1.2.1 (f))

Pass with rectification

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

MOT #15

2021-03-24 16:51

MOT test number

794976429874

Result

✓ Passed

MOT #14

2021-03-19 11:41

MOT test number

600427351622

Result

✗ Failed

Fail

Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail

Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

**MOT #13** 2020-03-17 10:35**MOT test number** 555429323549**Result** ✓ Passed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #12** 2020-03-17 10:35**MOT test number** 522745148262**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #11** 2019-03-19 12:18**MOT test number** 231020432281**Result** ✓ Passed**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10** 2018-03-14 13:56**MOT test number** 590960705360**Result** ✓ Passed

**MOT #9**

2018-03-13 12:34

MOT test number

814919535496

Result

✗ Failed

Fail Nearside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement d bush (2.4.G.2)

Fail Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)

Fail Offside Front Anti-roll bar rubber mounting deteriorated resulting in excessive movement d bush (2.4.G.2)

MOT #8

2017-03-10 09:44

MOT test number

682041102473

Result

✓ Passed

Advice Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7

2016-03-18 13:45

MOT test number

948353302436

Result

✓ Passed

Advice Nail n/s/r tyre

Advice Brake pipe slightly corroded front to rear (3.6.B.2c)

Advice Rear Direction indicator slightly discoloured both (1.4.A.2f)

Advice Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6

2015-03-30 10:10

MOT test number

845879185047

Result

✓ Passed

Advice Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

Advice Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #5** 2014-03-24 11:21**MOT test number** 566463884073**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #4** 2013-03-12 17:27**MOT test number** 185421673421**Result** ✓ Passed**MOT #3** 2013-03-09 12:19**MOT test number** 117168263416**Result** ✗ Failed**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #2** 2012-03-29 15:00**MOT test number** 645159182090**Result** ✓ Passed**MOT #1** 2012-03-29 09:10**MOT test number** 737849882046**Result** ✗ Failed**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)



Tax & MOT check

✕
Untaxed

Tax expired:
1 September 2023

✓
MOT

Expires:
12 July 2024

Tax status	Expired at 1 September
Days left	240 days too late
MOT expiry date	12 July 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	REXXXX
Plate since	2024-03-29
Current registration	REXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-03-31
Last registration	2023-07-13
Complete history	See info



Registration #1	2009-03-31	14 mi
Registration #2	2012-03-29	73.192 mi
Registration #3	2012-03-29	73.204 mi
Registration #4	2013-03-09	94.544 mi
Registration #5	2013-03-12	94.547 mi
Registration #6	2014-03-24	96.317 mi
Registration #7	2015-03-30	98.703 mi
Registration #8	2016-03-18	101.162 mi
Registration #9	2017-03-10	103.734 mi
Registration #10	2018-03-13	106.361 mi
Registration #11	2018-03-14	106.381 mi
Registration #12	2019-03-20	109.977 mi
Registration #13	2019-03-20	109.977 mi
Registration #14	2019-03-20	109.977 mi
Registration #15	2019-03-20	109.977 mi
Registration #16	2019-03-20	109.977 mi
Registration #17	2019-03-20	109.977 mi
Registration #18	2019-03-20	109.977 mi
Registration #19	2019-03-20	109.977 mi
Registration #20	2019-03-20	109.977 mi
Registration #21	2019-03-20	109.977 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1945 mm
Length	4782 mm
Kerb weight	1678 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	C008646