



DFI2GX0

report date: 2024-03-29

General information

Make	MAZDA
Model	2 TAMURA
Colour	Red
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	83 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-11-15
Pictures	8
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-26
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #12 2023-06-07 12:11

MOT test number 218767213029

Result ✓ Passed

Next expiry date 2024-06-06

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

MOT #11 2022-06-06 14:40

MOT test number 457595131066

Result ✓ Passed

Advice Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))

Advice Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #10 2021-06-05 08:36

MOT test number 419670975145

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2021-05-27 13:49**MOT test number** 837355782057**Result** ✗ Failed**Fail** Nearside Front Brake hose connection leaking on a hydraulic braking system ferrule (1.1.12 (c) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2020-07-20 15:38**MOT test number** 280661112678**Result** ✓ Passed**MOT #7** 2020-07-20 11:20**MOT test number** 445279291995**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-07-09 15:21**MOT test number** 544555092478**Result** ✓ Passed**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #5** 2019-07-09 09:03**MOT test number** 572006856953**Result** ✗ Failed**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))**MOT #4** 2018-07-04 09:23**MOT test number** 790685720802**Result** ✓ Passed**MOT #3** 2017-07-22 09:29**MOT test number** 380531868381**Result** ✓ Passed**MOT #2** 2016-07-23 08:57**MOT test number** 185029503074**Result** ✓ Passed**Advice** Nearside front tyre dot code 281=25 years old**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside front tyre worn on inner edge**MOT #1** 2015-07-21 17:04**MOT test number** 287562905215**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
6 June 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-07-31
Last registration	2023-06-07
Complete history	See info



Registration #1	2012-07-31	18 mi
Registration #2	2015-07-21	59.478 mi
Registration #3	2016-07-23	78.217 mi
Registration #4	2017-07-22	93.489 mi
Registration #5	2018-07-04	109.064 mi
Registration #6	2019-07-09	127.785 mi
Registration #7	2019-07-09	127.785 mi
Registration #8	2020-07-20	144.356 mi
Registration #9	2021-06-29	161.337 mi
Registration #10	2022-06-29	178.318 mi
Registration #11	2023-06-07	195.299 mi
Registration #12	2023-06-07	195.299 mi
Registration #13	2023-06-07	195.299 mi
Registration #14	2023-06-07	195.299 mi
Registration #15	2023-06-07	195.299 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	ZJ A50824