





report date: 2024-03-29

General information

| Make | HYUNDAI |
|---------------------|----------------|
| Model | IX35 CRDI SE |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 1.250 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-06-17

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-02-24 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 18 |
| Total items failed | 0 |

| MOT #8 | | 2024-02-16 16:16 |
|----------------------|---|------------------|
| MOT test | number | 114993077863 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-24 |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Handbrake travel high | |
| Advice | Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice binding (1 | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened .1.14 (a) (ii)) | heated / due to |
| Advice | Nearside Rear Service brake binding but not excessively (1.2.1 (f)) | |

| MOT #7 | 2023-02-23 16:59 |
|--|------------------|
| MOT test number | 327129020491 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #6 | 2022-02-21 14:08 |
|--|------------------|
| MOT test number | 667385499131 |
| Result | ✓ Passed |
| Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt | |

CarCheck.co.uk page 3/12



EK15XKX

report date: 2024-03-29

| MOT #5 | | 2021-02-24 12:05 |
|----------|---|------------------|
| MOT test | number | 847008879540 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #4 | | 2021-02-16 13:50 |
|----------|---|------------------|
| MOT test | number | 377231657412 |
| Result | | × Failed |
| MAJOR | Nearside Side repeater not working (4.4.1 (a) (ii)) | |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #3 | 2020-02-25 16:48 |
|---|------------------|
| MOT test number | 878949308688 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2019-08-02 14:16 |
| MOT test number | 657212950610 |
| Result | ✓ Passed |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 4/12



MOT #1 2018-05-23 09:39

MOT test number 419079644565 Result ✓ Passed **Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Under trays fitted Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 246 |
| MOT expiry date | 24 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r | |
|---|-------------|
| | |
| | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | IK UK |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 0.1.116 | |

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-03-30 |
| Last registration | 2024-02-16 |
| Complete history | See info |



| Registration #1 | 2015-03-30 | 8 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-05-23 | 25.335 mi |
| Registration #3 | 2019-08-02 | 36.030 mi |
| Registration #4 | 2020-02-25 | 40.050 mi |
| Registration #5 | 2021-02-16 | 49.412 mi |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | |
| Registration #6 | | |
| Registration #9 | | 11.777 mi |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 88% |
| Pedestrian | 54% |
| Safety systems | 71% |
| Overall rating | 81% |
| Video | see crash video |



Dimensions & weight

| Width | 1820 mm |
|---------------------|---------|
| Height | 1665 mm |
| Length | 4410 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1537 kg |
| Max. allowed weight | 1940 kg |

Additional information

| Fuel tank capacity | 58 I | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 pa | age 12/12 |

Number of axles 2

Engine number D4FDFZ359220